


INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)



FCC ID: YKBGFIVE-019

IC: 9095A-GFIVE019



INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)



FCC ID: YKBGFIVE-019

IC: 9095A-GFIVE019


INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)



FCC ID: YKBGFIVE-019

IC: 9095A-GFIVE019



INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15031350HKG-001

Equipment Photographs

Model: G5

(Internal)



FCC ID: YKBGFIVE-019

IC: 9095A-GFIVE019