



Federal Communications Commission

7435 Oakland Mills Road
Columbia, MD 21046-1609

Curtis-Straus LLC
Certification Department – TCB/FCB
527 Great Road
Littleton, MA 01460

4.20.2018

June 11, 2020

LABELING FOR FCC ID : YSG1614 and YSG1311 (DR & and SR families for models ALIZEA and CELEA)

To Whom It May Concern :

SORIN CRM S.A.S.
A MICROPORT CRM COMPANY
4, AVENUE REAUMUR
92140 CLAMART
FRANCE

CONTACT
T +33 (0)1 46 01 33 33

SHARE CAPITAL 104 825 140 €.
RCS NANTERRE 309 786 481

The equipment is implanted in the human body therefore the label with FCC ID is not feasible. Pursuant to sections 47 CFR 2.926 (e), we are proposing two following alternative methods:

- 1) The FCC ID and the statements required are in the User Manual (section 9)
- 2) The FCC ID appears on the package label which is affixed to the shipping box

Sincerely,

MICROPORT CRM
HEADQUARTER OFFICES
4, AVENUE REAUMUR
92140 CLAMART
FRANCE

Kathleen Vittum
PRINCIPAL REGULATORY SPECIALIST
MicroPort CRM
Direct Tel. – 651-238-6017
Email – Kathy.vittum@crm.microport.com

crm.microport.com