



802.11ac80\_5290MHz\_Chain 0 75.800MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 15:46:27

802.11ac80\_5290MHz\_Chain 1 75.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 18:20:03

802.11ac80\_5290MHz\_Chain 2 75.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:22:07

802.11ax160\_5250MHz\_RU\_Full\_Chain 0 156MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:22:39

802.11ax160\_5250MHz\_RU\_Full\_Chain 1  
156MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 18:23:43

802.11ax160\_5250MHz\_RU\_Full\_Chain 2  
155.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:26:41

802.11ax20\_5260MHz\_RU\_Full\_Chain 0  
19.050MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 15:57:42

802.11ax20\_5280MHz\_RU\_Full\_Chain 0 19MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 15:58:59

802.11ax20\_5320MHz\_RU\_Full\_Chain 0  
19.100MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 16:00:17

802.11ax20\_5260MHz\_RU\_Full\_Chain 1 19MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 18:30:45

802.11ax20\_5280MHz\_RU\_Full\_Chain 1 19MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 18:32:03

802.11ax20\_5320MHz\_RU\_Full\_Chain 1  
19.150MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 18:33:17

802.11ax20\_5260MHz\_RU\_Full\_Chain 2 19MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:33:50

802.11ax20\_5280MHz\_RU\_Full\_Chain 2 19MHz




ProjectNo.:2401Y27848E-RF Testert:Allen Bai  
Date: 18.DEC.2024 20:35:13

802.11ax20\_5320MHz\_RU\_Full\_Chain 2  
19.100MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:39:22

802.11ax40\_5270MHz\_RU\_Full\_Chain 0  
37.400MHz




ProjectNo.:2401Y27848E-RF Testert:Allen Bai  
Date: 18.DEC.2024 16:06:10

802.11ax40\_5310MHz\_RU\_Full\_Chain 0  
37.800MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:07:16


802.11ax40\_5270MHz\_RU\_Full\_Chain 1  
37.600MHz




ProjectNo.:2401Y27848E-RF Testert:Allen Bai  
Date: 18.DEC.2024 18:39:00

802.11ax40\_5310MHz\_RU\_Full\_Chain 1  
37.800MHz


ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 18:39:59

802.11ax40\_5270MHz\_RU\_Full\_Chain 2  
37.600MHz

ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:43:38


802.11ax40\_5310MHz\_RU\_Full\_Chain 2  
37.700MHz

ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:44:42


802.11ax80\_5290MHz\_RU\_Full\_Chain 0  
77.200MHz

ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:11:46

## 802.11ax80\_5290MHz\_RU\_Full\_Chain 1 77MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 18:43:11

802.11ax80\_5290MHz\_RU\_Full\_Chain 2  
77.200MHz

ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:48:20


5470-5725MHz

802.11a\_5500MHz\_Chain 0 16.850MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:32:57

802.11a\_5580MHz\_Chain 0 16.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:34:01

802.11a\_5700MHz\_Chain 0 16.900MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:35:17

802.11a\_5720MHz\_Chain 0 16.800MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:36:17

802.11a\_5500MHz\_Chain 1 16.800MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 18:46:44

802.11a\_5580MHz\_Chain 1 16.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 18:47:42

802.11a\_5700MHz\_Chain 1 16.750MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 18:48:49

802.11a\_5720MHz\_Chain 1 16.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 18:50:22

802.11a\_5500MHz\_Chain 2 16.750MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:51:11

802.11a\_5580MHz\_Chain 2 16.650MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:52:12

802.11a\_5700MHz\_Chain 2 16.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:53:29


802.11a\_5720MHz\_Chain 2 16.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 20:54:31




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 17:19:13




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:22:22




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:30:44



ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:50:12




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:51:35




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:53:43

802.11ac20\_5720MHz\_Chain 0 17.700MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 16:55:33

802.11ac20\_5500MHz\_Chain 1 17.900MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 18:59:56

802.11ac20\_5580MHz\_Chain 1 17.650MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:00:54

802.11ac20\_5700MHz\_Chain 1 17.850MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:02:09

802.11ac20\_5720MHz\_Chain 1 17.650MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:03:09

802.11ac20\_5500MHz\_Chain 2 17.900MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:05:20


## 802.11ac20\_5580MHz\_Chain 2 17.650MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai

Date: 18.DEC.2024 21:07:05


## 802.11ac20\_5700MHz\_Chain 2 17.850MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai

Date: 18.DEC.2024 21:08:21


## 802.11ac20\_5720MHz\_Chain 2 17.700MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai

Date: 18.DEC.2024 21:07:21


## 802.11ac40\_5510MHz\_Chain 0 36.500MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai

Date: 18.DEC.2024 17:06:42


## 802.11ac40\_5550MHz\_Chain 0 36.300MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai

Date: 18.DEC.2024 17:07:10


## 802.11ac40\_5670MHz\_Chain 0 36.600MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai


Date: 18.DEC.2024 17:07:36

802.11ac40\_5710MHz\_Chain 0 36.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 17:08:06

802.11ac40\_5510MHz\_Chain 1 36.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:12:30

802.11ac40\_5550MHz\_Chain 1 36.100MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:13:00

802.11ac40\_5670MHz\_Chain 1 36.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:13:32

802.11ac40\_5710MHz\_Chain 1 36.100MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:14:02

802.11ac40\_5510MHz\_Chain 2 36.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:19:26

802.11ac40\_5550MHz\_Chain 2 36.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:19:56

802.11ac40\_5670MHz\_Chain 2 36.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:20:32

802.11ac40\_5710MHz\_Chain 2 36.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:21:07

802.11ac80\_5530MHz\_Chain 0 75.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 17:13:42

802.11ac80\_5610MHz\_Chain 0 75.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 17:14:20

802.11ac80\_5690MHz\_Chain 0 75MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 17:14:54

802.11ac80\_5530MHz\_Chain 1 75.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:18:07

802.11ac80\_5610MHz\_Chain 1 75.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:18:44

802.11ac80\_5690MHz\_Chain 1 75MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:19:21

802.11ac80\_5530MHz\_Chain 2 75.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:26:31

802.11ac80\_5610MHz\_Chain 2 75.400MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:27:10

802.11ac80\_5690MHz\_Chain 2 75.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:27:51

802.11ax160\_5570MHz\_RU\_Full\_Chain 0  
155.600MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 17:44:49

802.11ax160\_5570MHz\_RU\_Full\_Chain 1  
155.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:50:24

802.11ax160\_5570MHz\_RU\_Full\_Chain 2  
155.200MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:31:31

802.11ax20\_5500MHz\_RU\_Full\_Chain 0  
19.150MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 17:22:03

802.11ax20\_5580MHz\_RU\_Full\_Chain 0 19MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 17:23:01

802.11ax20\_5700MHz\_RU\_Full\_Chain 0  
19.100MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 17:24:07

802.11ax20\_5720MHz\_RU\_Full\_Chain 0  
19MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 17:25:02

802.11ax20\_5500MHz\_RU\_Full\_Chain 1  
19.100MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:25:16

802.11ax20\_5580MHz\_RU\_Full\_Chain 1  
19MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:26:16

802.11ax20\_5700MHz\_RU\_Full\_Chain 1  
19.150MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:27:29

802.11ax20\_5720MHz\_RU\_Full\_Chain 1  
19MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 19:28:31

802.11ax20\_5500MHz\_RU\_Full\_Chain 2  
19.100MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai  
Date: 18.DEC.2024 21:33:59

802.11ax20\_5580MHz\_RU\_Full\_Chain 2  
18.950MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 21:34:59

802.11ax20\_5700MHz\_RU\_Full\_Chain 2  
19.050MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 21:36:12

802.11ax20\_5720MHz\_RU\_Full\_Chain 2  
18.950MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 21:37:10

802.11ax40\_5510MHz\_RU\_Full\_Chain 0  
37.700MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 17:34:51

802.11ax40\_5550MHz\_RU\_Full\_Chain 0  
37.600MHz



ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 17:35:21

802.11ax40\_5670MHz\_RU\_Full\_Chain 0  
37.800MHz



ProjectNo.:2401Y27848E-RF Testerr:Allen Bai  
Date: 18.DEC.2024 17:35:49