

Photo of Conducted Emission Measurement

Test mode: Full Load

Adapter 1:





Adapter 2:



Photo of Radiated Emission Measurement (Below 1G)

Test Mode: Full Load

Adapter 1:



Adapter 2:







Photo of Radiated Emission Measurement (Above 1G)

Test Mode: Full Load

Adapter 1:



Adapter 2:

