



TEST SETUP PHOTOS




[EMC Technologies Pty Ltd](http://www.emctech.com.au)

176 Harrick Road, Keilor Park, Victoria 3042, Australia

Ph: + 61 (0)3 9365 1000, Email: sales@emctech.com.au, Web: www.emctech.com.au

TEST SETUP PHOTOS



[EMC Technologies Pty Ltd](#)

176 Harrick Road, Keilor Park, Victoria 3042, Australia

Ph: + 61 (0)3 9365 1000, Email: sales@emctech.com.au, Web: www.emctech.com.au

TEST SETUP PHOTOS




[EMC Technologies Pty Ltd](#)

176 Harrick Road, Keilor Park, Victoria 3042, Australia

Ph: + 61 (0)3 9365 1000, Email: sales@emctech.com.au, Web: www.emctech.com.au

TEST SETUP PHOTOS




[EMC Technologies Pty Ltd](#)

176 Harrick Road, Keilor Park, Victoria 3042, Australia

Ph: + 61 (0)3 9365 1000, Email: sales@emctech.com.au, Web: www.emctech.com.au

TEST SETUP PHOTOS



[EMC Technologies Pty Ltd](#)

176 Harrick Road, Keilor Park, Victoria 3042, Australia

Ph: + 61 (0)3 9365 1000, Email: sales@emctech.com.au, Web: www.emctech.com.au


M2112041-5
APPENDIX D – PHOTOS

12 APPENDIX D – PHOTOS

Survey Point 1-7



Survey Point 8 (E/H-Field Spatial Averaging)



Separation Distance

