

Statement

Because there is no component in position R31, So R31 disconnect, therefore there is



no transmitter from antenna port ANT 1 permanently . Only chip



antenna ANT 2 can transmit

Signature: *Albert Miao*

Title: Hardware Engineer

Date: 2016-4-12

Seeed Technology Co., Ltd.