

---


## INTERTEK TESTING SERVICE

Report No.: 16081243HKG-003

### Equipment Photographs

Model : FL2016F

(Internal)



## INTERTEK TESTING SERVICE


---

Report No.: 16081243HKG-003

### Equipment Photographs

Model : FL2016F

(Internal)





# INTERTEK TESTING SERVICE

Report No.: 16081243HKG-003

## Equipment Photographs

Model : FL2016F

(Internal)



## INTERTEK TESTING SERVICE


---

Report No.: 16081243HKG-003

### Equipment Photographs

Model : FL2016F

(Internal)



## INTERTEK TESTING SERVICE


---

Report No.: 16081243HKG-003

### Equipment Photographs

Model : FL2016F

(Internal)



## INTERTEK TESTING SERVICE


---

Report No.: 16081243HKG-003

### Equipment Photographs

Model : FL2016F

(Internal)



## INTERTEK TESTING SERVICE



---

Report No.: 16081243HKG-003

### Equipment Photographs

Model : FL2016F

(Internal)



## INTERTEK TESTING SERVICE

---

Report No.: 16081243HKG-003

### Equipment Photographs

Model : FL2016F

(Internal)



## INTERTEK TESTING SERVICE


---

Report No.: 16081243HKG-003

### Equipment Photographs

Model : FL2016F

(Internal)



## INTERTEK TESTING SERVICE

---

Report No.: 16081243HKG-003

### Equipment Photographs

Model : FL2016F

(Internal)



## **INTERTEK TESTING SERVICE**

---

Report No.: 16081243HKG-003

### **Equipment Photographs**

**Model : FL2016F**

**(Internal)**

