





Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 18GHz~40GHz



Date: 22 NOV. 2017 14:16:13


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 18GHz~40GHz



Date: 22 NOV. 2017 14:06:15




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 22.NOV.2017 14:15:42


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 22.NOV.2017 14:06:37




Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 18GHz~40GHz



Date: 22 NOV. 2017 14:12:09


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 18GHz~40GHz



Date: 22 NOV. 2017 14:08:24




Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 22 NOV 2017 14:12:38


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 22 NOV 2017 14:07:52




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 18GHz~40GHz



Date: 22 NOV. 2017 14:11:13


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 18GHz~40GHz



Date: 22 NOV. 2017 14:08:19




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 22.NOV.2017 14:10:42


Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 22.NOV.2017 14:09:43




Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 18GHz~40GHz



Date: 17,NOV,2017 17:04:26


Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 18GHz~40GHz



Date: 17,NOV,2017 17:05:12




Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 17,NOV,2017 17:03:09


Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 17,NOV,2017 17:03:30




Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 18GHz~40GHz



Date: 19.NOV.2017 01:28:40


Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 18GHz~40GHz



Date: 19.NOV.2017 01:30:24




Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 19.NOV.2017 01:27:12


Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 19.NOV.2017 01:31:54




Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 18GHz~40GHz



Date: 19.NOV.2017 01:55:04


Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 18GHz~40GHz



Date: 19.NOV.2017 01:58:05




Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 19.NOV.2017 01:58:01


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 19.NOV.2017 02:00:25




Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 18GHz~40GHz



Date: 19.NOV.2017 02:18:50


Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 18GHz~40GHz



Date: 19.NOV.2017 02:24:19




Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 19.NOV.2017 02:20:45


Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 19.NOV.2017 02:25:06




Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 18GHz~40GHz



Date: 19.NOV.2017 02:49:38


Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 18GHz~40GHz



Date: 19.NOV.2017 02:52:51




Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 19 NOV. 2017 02:50:31

Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 19 NOV. 2017 02:53:28

Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 18GHz~40GHz



Date: 19.NOV.2017 03:18:50


Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 18GHz~40GHz



Date: 19.NOV.2017 03:13:55




Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 19.NOV.2017 03:17:39

Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 19.NOV.2017 03:14:32




For Antenna 3:

Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 1GHz~3GHz



Date: 21.NOV.2017 10:51:18


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 1GHz~3GHz



Date: 21.NOV.2017 10:58:25




Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 21.NOV.2017 10:51:51


Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 21.NOV.2017 10:57:58




Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 1GHz~3GHz



Date: 21.NOV.2017 10:55:26


Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 1GHz~3GHz



Date: 21.NOV.2017 10:59:02




Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 21,NOV,2017 10:53:47


Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 21,NOV,2017 10:59:25




Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 1GHz~3GHz



Date: 21.NOV.2017 10:56:06


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 1GHz~3GHz



Date: 21.NOV.2017 11:00:27




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 21,NOV,2017 10:56:34


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 21,NOV,2017 11:00:03




Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 1GHz~3GHz



Date: 21.NOV.2017 11:06:05


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 1GHz~3GHz



Date: 21.NOV.2017 11:05:04




Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 21.NOV.2017 11:09:02


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 21.NOV.2017 11:05:25




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 1GHz~3GHz



Date: 21.NOV.2017 11:10:38


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 1GHz~3GHz



Date: 21.NOV.2017 11:08:40




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 21,NOV,2017 11:09:54


Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 21,NOV,2017 11:08:10




Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 1GHz~3GHz



Date: 18.NOV.2017 09:15:59


Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 1GHz~3GHz



Date: 18.NOV.2017 09:10:51




Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 18.NOV.2017 09:34:16


Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 18.NOV.2017 09:34:25




Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 1GHz~3GHz



Date: 18.NOV.2017 09:17:11


Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 1GHz~3GHz



Date: 18.NOV.2017 09:17:25




Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 18.NOV.2017 09:34:46


Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 18.NOV.2017 09:34:55




Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 1GHz~3GHz



Date: 18.NOV.2017 09:21:58


Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 1GHz~3GHz



Date: 18.NOV.2017 09:22:39




Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 18.NOV.2017 09:35:13


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 18.NOV.2017 09:35:26




Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 1GHz~3GHz



Date: 18.NOV.2017 22:42:43


Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 1GHz~3GHz



Date: 18.NOV.2017 23:12:24




Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 18.NOV.2017 22:43:50


Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 18.NOV.2017 23:14:08




Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 1GHz~3GHz



Date: 18.NOV.2017 23:20:56


Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 1GHz~3GHz



Date: 19.NOV.2017 00:05:14




Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 18 NOV 2017 23:21:54


Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 19 NOV 2017 00:05:58




Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 1GHz~3GHz



Date: 19.NOV.2017 00:11:29

Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 1GHz~3GHz



Date: 19.NOV.2017 00:52:35