





Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 19.NOV.2017 00:12:21


Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 19.NOV.2017 00:53:35




Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 16:42:36


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 16:53:40




Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 21.NOV.2017 15:43:33

Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 21.NOV.2017 16:08:27

Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 16:45:03


Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 16:10:31




Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 21.NOV.2017 15:46:00

Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 21.NOV.2017 16:10:59

Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 15:47:07


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 16:12:27




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 15:47:26


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 16:12:00




Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 3GHz~6GHz



Date: 21,NOV,2017 15:48:14


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 3GHz~6GHz



Date: 21,NOV,2017 15:51:42




Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 21,NOV.2017 15:48:31


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 21,NOV.2017 15:51:57




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 16:49:12


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 15:50:47




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 21.NOV.2017 15:49:23


Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 21.NOV.2017 16:51:00




Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 09:46:39


Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 09:52:57




Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 09:48:39


Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 09:53:55




Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 10:27:19


Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 10:05:26




Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 18.NOV.2017 10:28:55

Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 18.NOV.2017 10:09:55

Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 10:44:00


Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 11:00:17




Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 10:44:31


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 11:01:12




Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 22:32:20


Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 23:06:21




Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 22:38:04


Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 23:07:36




Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 23:24:09


Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 3GHz~6GHz



Date: 18.NOV.2017 23:58:01




Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 18.NOV.2017 23:32:24


Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 19.NOV.2017 00:02:43




Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 3GHz~6GHz



Date: 19.NOV.2017 00:13:51


Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 3GHz~6GHz



Date: 19.NOV.2017 00:45:45




Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 19.NOV.2017 00:14:47


Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 19.NOV.2017 00:49:24




Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 15:29:10


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 15:24:41




Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 16:29:21


Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 16:24:17




Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 6GHz~9GHz



Date: 21,NOV,2017 15:30:11


Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 6GHz~9GHz



Date: 21,NOV,2017 15:25:36




Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 16:29:51


Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 16:25:48




Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 15:30:43


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 15:28:31




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 15:30:56


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 15:28:16




Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 6GHz~9GHz




Date: 21.NOV.2017 16:32:07

Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 6GHz~9GHz




Date: 21.NOV.2017 16:27:12

Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 15:31:28


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 15:27:24




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 6GHz~9GHz



Date: 21,NOV,2017 15:33:06


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 6GHz~9GHz



Date: 21,NOV,2017 16:28:05




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 21.NOV.2017 15:33:16


Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 21.NOV.2017 16:27:47




Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:34:13


Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:11:41




Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:34:36


Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:29:50




Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:37:17


Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:08:06




Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:38:06


Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:08:34




Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:40:14


Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:05:56




Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 11:39:08


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 11:06:54




Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 6GHz~9GHz



Date: 18.NOV.2017 22:44:56


Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 6GHz~9GHz



Date: 18.NOV.2017 23:02:11




Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 18.NOV.2017 22:45:46

Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 18.NOV.2017 23:02:47

Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 6GHz~9GHz




Date: 18.NOV.2017 23:33:55

Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 6GHz~9GHz




Date: 18.NOV.2017 23:55:01

Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 18.NOV.2017 23:34:39

Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 18.NOV.2017 23:55:47

Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 6GHz~9GHz



Date: 19.NOV.2017 00:17:50


Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 6GHz~9GHz



Date: 19.NOV.2017 00:41:11




Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 19.NOV.2017 00:18:39


Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 19.NOV.2017 00:42:42




Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 14:35:06


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:04:37




Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 14:35:48


Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:07:21




Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 9GHz~18GHz



Date: 21,NOV,2017 14:37:33


Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 9GHz~18GHz



Date: 21,NOV,2017 12:08:43




Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 14:37:01


Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:08:11




Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 14:43:00


Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:09:17




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 21.NOV.2017 14:43:39

Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 21.NOV.2017 12:08:51

Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 12:13:38


Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:10:02




Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 12:13:13


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:10:20




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 9GHz~18GHz



Date: 21.NOV.2017 12:12:10


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:11:10




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 21.NOV.2017 12:12:38


Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 21.NOV.2017 12:10:47




Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 9GHz~18GHz




Date: 18.NOV.2017 11:59:37

Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 9GHz~18GHz



Date: 18.NOV.2017 12:23:48



Spectrum

Ref Level -8.50 dBm Offset 1.50 dB RBW 1 MHz

Att 0 dB SWR 36 ms VBW 3 MHz Mode Auto Sweep

● 1Pk View

M1[1]

-53.14 dBm
17.2250 GHz

Start 9.0 GHz 691 pts Stop 18.0 GHz

Spectrum

Ref Level -8.50 dBm Offset 1.50 dB RBW 1 MHz

Att 0 dB BW 36 ms VBW 3 MHz Mode Auto Sweep

● 1PK View

M1[1] -53.72 dBm 11.9940 GHz


M2

Start 9.0 GHz 691 pts Stop 18.0 GHz

Issued Date : Dec. 27, 2017




Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 9GHz~18GHz



Date: 18.NOV.2017 12:03:30


Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 9GHz~18GHz



Date: 18.NOV.2017 12:22:07




Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 18.NOV.2017 12:05:27

Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 18.NOV.2017 12:22:37

Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 9GHz~18GHz



Date: 18.NOV.2017 12:17:15

Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 9GHz~18GHz



Date: 18.NOV.2017 12:20:23