



Plot on Configuration VHT20 / 5300 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 4 APR. 2018 01:02:04

Plot on Configuration VHT20 / 5300 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 4 APR. 2018 01:04:45

Plot on Configuration VHT20 / 5300 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 4 APR. 2018 01:19:20

Plot on Configuration VHT20 / 5300 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 4 APR. 2018 01:21:28

Plot on Configuration VHT20 / 5320 MHz / Average / Port 1 / 6GHz~9GHz




Date: 4 APR.2018 01:32:32

Plot on Configuration VHT20 / 5320 MHz / Average / Port 2 / 6GHz~9GHz




Date: 4 APR.2018 01:34:34

Plot on Configuration VHT20 / 5320 MHz / Average / Port 3 / 6GHz~9GHz




Date: 4 APR. 2018 01:47:08

Plot on Configuration VHT20 / 5320 MHz / Average / Port 4 / 6GHz~9GHz




Date: 4 APR. 2018 01:21:28

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 4 APR.2018 01:32:32

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 4 APR.2018 01:34:34

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 4 APR.2018 01:47:08

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 4 APR.2018 01:49:22

Plot on Configuration VHT40 / 5270 MHz / Average / Port 1 / 6GHz~9GHz




Date: 4 APR. 2018 02:01:48

Plot on Configuration VHT40 / 5270 MHz / Average / Port 2 / 6GHz~9GHz




Date: 4 APR. 2018 02:03:44

Plot on Configuration VHT40 / 5270 MHz / Average / Port 3 / 6GHz~9GHz




Date: 4.APR.2018 02:17:03

Plot on Configuration VHT40 / 5270 MHz / Average / Port 4 / 6GHz~9GHz




Date: 4.APR.2018 02:20:18

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 4 APR. 2018 02:02:27

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 4 APR. 2018 02:04:30

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 4 APR. 2018 02:18:30

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 4 APR. 2018 02:20:56

Plot on Configuration VHT40 / 5310 MHz / Average / Port 1 / 6GHz~9GHz




Date: 4 APR.2018 02:32:25

Plot on Configuration VHT40 / 5310 MHz / Average / Port 2 / 6GHz~9GHz




Date: 4 APR.2018 02:34:18

Plot on Configuration VHT40 / 5310 MHz / Average / Port 3 / 6GHz~9GHz




Date: 4.APR.2018 02:42:40

Plot on Configuration VHT40 / 5310 MHz / Average / Port 4 / 6GHz~9GHz




Date: 4.APR.2018 02:44:38

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 4 APR. 2018 02:33:06

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 4 APR. 2018 02:34:52

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 4 APR.2018 02:43:17

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 4 APR.2018 02:45:18

Plot on Configuration VHT80 / 5290 MHz / Average / Port 1 / 6GHz~9GHz




Date: 6.APR.2018 20:18:13

Plot on Configuration VHT80 / 5290 MHz / Average / Port 2 / 6GHz~9GHz




Date: 6.APR.2018 20:21:41

Plot on Configuration VHT80 / 5290 MHz / Average / Port 3 / 6GHz~9GHz




Date: 6.APR.2018 20:38:03

Plot on Configuration VHT80 / 5290 MHz / Average / Port 4 / 6GHz~9GHz




Date: 6.APR.2018 20:41:12

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 6.APR.2018 20:18:57

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 6.APR.2018 20:23:15

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 6.APR.2018 20:39:32

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 6.APR.2018 20:42:24

Plot on Configuration VHT20 / 5500 MHz / Average / Port 1 / 6GHz~9GHz




Date: 31.MAR.2018 22:33:29

Plot on Configuration VHT20 / 5500 MHz / Average / Port 2 / 6GHz~9GHz




Date: 31.MAR.2018 22:35:47

Plot on Configuration VHT20 / 5500 MHz / Average / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 22:47:11

Plot on Configuration VHT20 / 5500 MHz / Average / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 22:50:00

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 31.MAR.2018 22:34:18

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 31.MAR.2018 22:36:27

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 22:48:35

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 22:51:03

Plot on Configuration VHT20 / 5580 MHz / Average / Port 1 / 6GHz~9GHz




Date: 31.MAR.2018 23:11:07

Plot on Configuration VHT20 / 5580 MHz / Average / Port 2 / 6GHz~9GHz




Date: 31.MAR.2018 23:16:06

Plot on Configuration VHT20 / 5580 MHz / Average / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 23:26:56

Plot on Configuration VHT20 / 5580 MHz / Average / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 23:31:17

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 31.MAR.2018 23:11:54

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 31.MAR.2018 23:17:06

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 23:27:42

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 23:32:19

Plot on Configuration VHT20 / 5700 MHz / Average / Port 1 / 6GHz~9GHz




Date: 31.MAR.2018 23:43:35

Plot on Configuration VHT20 / 5700 MHz / Average / Port 2 / 6GHz~9GHz




Date: 31.MAR.2018 23:45:36

Plot on Configuration VHT20 / 5700 MHz / Average / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 23:56:26

Plot on Configuration VHT20 / 5700 MHz / Average / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 23:58:40

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 31.MAR.2018 23:44:15

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 31.MAR.2018 23:44:15

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 23:57:07

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 23:59:25

Plot on Configuration VHT20 / 5720 MHz / Average / Port 1 / 6GHz~9GHz




Date: 1.APR.2018 00:10:28

Plot on Configuration VHT20 / 5720 MHz / Average / Port 2 / 6GHz~9GHz




Date: 1.APR.2018 00:12:41

Plot on Configuration VHT20 / 5720 MHz / Average / Port 3 / 6GHz~9GHz




Date: 1.APR.2018 00:25:11

Plot on Configuration VHT20 / 5720 MHz / Average / Port 4 / 6GHz~9GHz




Date: 1.APR.2018 00:27:22

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 1.APR.2018 00:11:12

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 1.APR.2018 00:13:32

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 1.APR.2018 00:25:58

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 1.APR.2018 00:28:25

Plot on Configuration VHT40 / 5510 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 01:50:37

Plot on Configuration VHT40 / 5510 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 01:53:36

Plot on Configuration VHT40 / 5510 MHz / Average / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 02:05:23

Plot on Configuration VHT40 / 5510 MHz / Average / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 02:10:29

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 01:51:22

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 01:54:14

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 02:06:01

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 02:11:24

Plot on Configuration VHT40 / 5550 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 02:32:01

Plot on Configuration VHT40 / 5550 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 02:34:39

Plot on Configuration VHT40 / 5550 MHz / Average / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 02:43.41

Plot on Configuration VHT40 / 5550 MHz / Average / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 02:45.54

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 02:32:53

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 02:35:27

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 02:44:27

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 02:46:57

Plot on Configuration VHT40 / 5670 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 20:15:19

Plot on Configuration VHT40 / 5670 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 20:20:35

Plot on Configuration VHT40 / 5670 MHz / Average / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 20:38:34

Plot on Configuration VHT40 / 5670 MHz / Average / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 20:42:50

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 20:16:23

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 20:21:47

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 20:39:36

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 20:45:47

Plot on Configuration VHT40 / 5710 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 21:00:29

Plot on Configuration VHT40 / 5710 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 21:03:45

Plot on Configuration VHT40 / 5710 MHz / Average / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 21:22:42

Plot on Configuration VHT40 / 5710 MHz / Average / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 21:26:13

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 21:01:56

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 21:04:23

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 21:23:35

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 21:27:17

Plot on Configuration VHT80 / 5530 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 21:50:18

Plot on Configuration VHT80 / 5530 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 21:57:39

Plot on Configuration VHT80 / 5530 MHz / Average / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 22:11:34

Plot on Configuration VHT80 / 5530 MHz / Average / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 22:13:55

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 21:51:33

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 21:58:59

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 22:12:29

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 22:15:45

Plot on Configuration VHT80 / 5610 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 22:34:22

Plot on Configuration VHT80 / 5610 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 22:37:29

Plot on Configuration VHT80 / 5610 MHz / Average / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 22:50:02

Plot on Configuration VHT80 / 5610 MHz / Average / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 22:56:44

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 22:35:10

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 22:38:35

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 22:52:22

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 22:57:56

Plot on Configuration VHT80 / 5690 MHz / Average / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 23:11:50

Plot on Configuration VHT80 / 5690 MHz / Average / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 23:14:06

Plot on Configuration VHT80 / 5690 MHz / Average / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 23:27:01

Plot on Configuration VHT80 / 5690 MHz / Average / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 23:29:26

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 3.APR.2018 23:12:33

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 3.APR.2018 23:14:44

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 3.APR.2018 23:28:07

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 3.APR.2018 23:30:10

Plot on Configuration VHT20 / 5260 MHz / Average / Port 1 / 9GHz~18GHz




Date: 6.APR.2018 21:03.48

Plot on Configuration VHT20 / 5260 MHz / Average / Port 2 / 9GHz~18GHz




Date: 6.APR.2018 21:13.43

Plot on Configuration VHT20 / 5260 MHz / Average / Port 3 / 9GHz~18GHz




Date: 6.APR.2018 21:18:35

Plot on Configuration VHT20 / 5260 MHz / Average / Port 4 / 9GHz~18GHz




Date: 6.APR.2018 21:29:23

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 6.APR.2018 21:04:54

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 6.APR.2018 21:14:25

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 6.APR.2018 21:19:54

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 6.APR.2018 21:30:14

Plot on Configuration VHT20 / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 6.APR.2018 21:33:30

Plot on Configuration VHT20 / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 6.APR.2018 21:43:58

Plot on Configuration VHT20 / 5300 MHz / Average / Port 3 / 9GHz~18GHz




Date: 6.APR.2018 21:47:12

Plot on Configuration VHT20 / 5300 MHz / Average / Port 4 / 9GHz~18GHz




Date: 6.APR.2018 22:00:27

Plot on Configuration VHT20 / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 6.APR.2018 21:34:34

Plot on Configuration VHT20 / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 6.APR.2018 21:44:47


Plot on Configuration VHT20 / 5300 MHz / Peak / Port 3 / 9GHz~18GHz



Plot on Configuration VHT20 / 5300 MHz / Peak / Port 4 / 9GHz~18GHz




Plot on Configuration VHT20 / 5320 MHz / Average / Port 1 / 9GHz~18GHz



Date: 6.APR.2018 22:04:53

Plot on Configuration VHT20 / 5320 MHz / Average / Port 2 / 9GHz~18GHz



Date: 6.APR.2018 22:16:05