





## Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 28 SEP 2017 17:18:03


## Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 28 SEP 2017 17:18:26



## Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 9GHz~18GHz




## Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 9GHz~18GHz






Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 28 SEP 2017 17:20:11


Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 28 SEP 2017 17:20:26




## Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 9GHz~18GHz




Date: 28 SEP 2017 17:20:49

## Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 9GHz~18GHz




Date: 28 SEP 2017 17:21:10

### Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 28 SEP 2017 17:21:28


### Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 28 SEP 2017 17:21:44




## Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 18GHz~40GHz



Date: 30.SEP.2017 08:31:40


## Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 18GHz~40GHz



Date: 30.SEP.2017 08:34:03




## Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 30 SEP 2017 08:34:43


## Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 30 SEP 2017 08:35:40




## Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 18GHz~40GHz



Date: 30.SEP.2017 08:37:57


## Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 18GHz~40GHz



Date: 30.SEP.2017 08:39:21




## Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 30.SEP.2017 08:44:41


## Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 30.SEP.2017 08:45:08




## Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 18GHz~40GHz



Date: 30 SEP.2017 08:51:08


## Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 18GHz~40GHz



Date: 30 SEP.2017 08:52:11




## Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 30 SEP 2017 08:52:43

## Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 30 SEP 2017 08:53:07

### Plot on Configuration QPSK, 80M / 5190 MHz / Average / Port 1 / 18GHz~40GHz



Date: 30 SEP 2017 11:46:05


### Plot on Configuration QPSK, 80M / 5190 MHz / Average / Port 2 / 18GHz~40GHz



Date: 30 SEP 2017 11:48:03




## Plot on Configuration QPSK, 80M / 5190 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 30 SEP 2017 11:49:05


## Plot on Configuration QPSK, 80M / 5190 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 30 SEP 2017 11:49:45




## Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 18GHz~40GHz



Date: 30 SEP 2017 11:51:15


## Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 18GHz~40GHz



Date: 30 SEP 2017 11:52:13




Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 30 SEP 2017 11:53:01


Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 30 SEP 2017 11:53:32




## Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 18GHz~40GHz



Date: 30.SEP.2017 11:57:00


## Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 18GHz~40GHz



Date: 30.SEP.2017 11:59:13




## Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 30 SEP 2017 12:01:03

## Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 30 SEP 2017 12:01:32

### Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28.SEP.2017 15:40:56


### Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 18GHz~40GHz



Date: 28.SEP.2017 15:41:47




## Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 28 SEP 2017 15:42:03

## Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 28 SEP 2017 15:42:22

### Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28.SEP.2017 15:43:03


### Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 18GHz~40GHz



Date: 28.SEP.2017 15:43:39




## Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 28 SEP 2017 15:43:55


## Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 28 SEP 2017 15:44:11




## Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28 SEP 2017 15:44:50


## Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 18GHz~40GHz



Date: 28 SEP 2017 15:45:38




Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 28.SEP.2017 15:45:54


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 28.SEP.2017 15:46:10




## Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28 SEP 2017 17:22:40


## Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 18GHz~40GHz




Date: 28 SEP 2017 17:23:13



## Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 18GHz~40GHz




## Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 18GHz~40GHz






## Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28 SEP 2017 17:24:33


## Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 18GHz~40GHz




Date: 28 SEP 2017 17:25:11



## Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 1 / 18GHz~40GHz




## Plot on Configuration QPSK, 80M / 5785 MHz / Peak / Port 2 / 18GHz~40GHz






## Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 1 / 18GHz~40GHz



Date: 28.SEP.2017 17:26:26


## Plot on Configuration QPSK, 80M / 5805 MHz / Average / Port 2 / 18GHz~40GHz




Date: 28.SEP.2017 17:27:01



## Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 1 / 18GHz~40GHz




## Plot on Configuration QPSK, 80M / 5805 MHz / Peak / Port 2 / 18GHz~40GHz






For Antenna 2:

Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 1 / 1GHz~3GHz



Date: 29 SEP 2017 16:33:47


Plot on Configuration QPSK, 20M / 5180 MHz / Average / Port 2 / 1GHz~3GHz




Date: 29 SEP 2017 16:34:00




## Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 1 / 1GHz~3GHz



## Plot on Configuration QPSK, 20M / 5180 MHz / Peak / Port 2 / 1GHz~3GHz




### Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 1 / 1GHz~3GHz



Date: 29.SEP.2017 16:34:41


### Plot on Configuration QPSK, 20M / 5200 MHz / Average / Port 2 / 1GHz~3GHz



Date: 29.SEP.2017 16:34:54




## Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 29.SEP.2017 16:35:05


## Plot on Configuration QPSK, 20M / 5200 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 29.SEP.2017 16:35:16




## Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 1 / 1GHz~3GHz



Date: 29 SEP 2017 16:35:35


## Plot on Configuration QPSK, 20M / 5240 MHz / Average / Port 2 / 1GHz~3GHz



Date: 29 SEP 2017 16:35:48




Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 29 SEP 2017 16:36:07


Plot on Configuration QPSK, 20M / 5240 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 29 SEP 2017 16:36:19




## Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 1 / 1GHz~3GHz



Date: 29 SEP 2017 21:08:18


## Plot on Configuration QPSK, 80M / 5200 MHz / Average / Port 2 / 1GHz~3GHz



Date: 29 SEP 2017 21:08:46




## Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 29 SEP 2017 21:07:22


## Plot on Configuration QPSK, 80M / 5200 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 29 SEP 2017 21:07:42




Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 1 / 1GHz~3GHz



Date: 29 SEP 2017 21:18:35


Plot on Configuration QPSK, 80M / 5210 MHz / Average / Port 2 / 1GHz~3GHz



Date: 29 SEP 2017 21:19:05




Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 29 SEP 2017 21:19:43


Plot on Configuration QPSK, 80M / 5210 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 29 SEP 2017 21:20:27




## Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 1 / 1GHz~3GHz



Date: 28 SEP 2017 00:46:19


## Plot on Configuration QPSK, 20M / 5745 MHz / Average / Port 2 / 1GHz~3GHz



Date: 28 SEP 2017 00:47:29




## Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 28 SEP 2017 00:48:43


## Plot on Configuration QPSK, 20M / 5745 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 28 SEP 2017 00:49:09




Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 1 / 1GHz~3GHz



Date: 28 SEP 2017 00:50:23


Plot on Configuration QPSK, 20M / 5785 MHz / Average / Port 2 / 1GHz~3GHz



Date: 28 SEP 2017 00:51:09




## Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 28 SEP 2017 00:51:52


## Plot on Configuration QPSK, 20M / 5785 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 28 SEP 2017 00:52:39




## Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 1 / 1GHz~3GHz



Date: 28 SEP 2017 00:54:01


## Plot on Configuration QPSK, 20M / 5825 MHz / Average / Port 2 / 1GHz~3GHz



Date: 28 SEP 2017 00:54:49




Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 28.SEP.2017 00:55:30


Plot on Configuration QPSK, 20M / 5825 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 28.SEP.2017 00:56:03




## Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 1 / 1GHz~3GHz



Date: 29.SEP.2017 10:37:56


## Plot on Configuration QPSK, 80M / 5765 MHz / Average / Port 2 / 1GHz~3GHz



Date: 29.SEP.2017 10:38:52




## Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 29 SEP 2017 10:39:13


## Plot on Configuration QPSK, 80M / 5765 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 29 SEP 2017 10:39:28




## Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 1 / 1GHz~3GHz



Date: 29 SEP 2017 10:39:45

## Plot on Configuration QPSK, 80M / 5785 MHz / Average / Port 2 / 1GHz~3GHz



Date: 29 SEP 2017 10:40:02