



Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 19:44:43

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 20:00:38

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 20:09:49

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 20:29:23

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 12.OCT.2017 20:10:24

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 12.OCT.2017 20:27:41



The screenshot shows a spectrum analyzer interface with the following settings and data:

- Windows:** Spectrum 2, Spectrum 3, Spectrum 4.
- Parameters:**
 - Ref Level: -8.50 dBm
 - Offset: 1.50 dB
 - RBW: 1 MHz
 - Att: 0 dB
 - SWT: 2.9 s
 - VBW: 1 kHz
 - Mode: Auto Sweep
- View:** 1Pk View
- Plot:** A frequency spectrum plot with a blue trace. The y-axis represents power in dBm, ranging from -100 to -20. The x-axis represents frequency in GHz, ranging from 5.400 to 5.406. A significant peak is labeled M1[1] at 5.40360 GHz with a level of -69.25 dBm. Another smaller peak is labeled M1 at approximately 5.402 GHz.
- Axis Labels:**
 - Start 5.40 GHz
 - Stop 5.406 GHz
 - 691 pts

The screenshot displays a spectrum analyzer interface with the following settings and data:


- Windows:** Spectrum 2, Spectrum 3, Spectrum 4.
- Ref Level:** -8.50 dBm
- Offset:** 1.50 dB
- RBW:** 1 MHz
- Att:** U dB
- SWI:** 2.9 s
- VBW:** 1 kHz
- Mode:** Auto Sweep
- View:** 1Pk View

The spectrum plot shows a signal with a peak at 77.40 dBm and 5.40300 GHz. The peak is labeled M1[1]. The plot also shows a smaller peak at 77.40 dBm and 5.40300 GHz, labeled M1.

Start: 3.0 GHz
Stop: 6.0 GHz
Resolution: 691 pts


Issued Date : Jul. 26, 2018

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 13.OCT.2017 01:00:05

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 13.OCT.2017 01:05:12

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 22:32:05

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 22:34:21

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 12.OCT.2017 22:32:43

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 22:33:39

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 22:30:20

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 22:27:56

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 22:29:33

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 22:28:38

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 22:23:38

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 22:26:22

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 22:24:42

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 22:25:32

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 3GHz~6GHz




Date: 13.OCT.2017 01:10:26

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 3GHz~6GHz




Date: 13.OCT.2017 01:14:44

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 13.OCT.2017 01:11:14

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 13.OCT.2017 01:13:45

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 6GHz~9GHz




Date: 16.OCT.2017 22:18:07

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 6GHz~9GHz




Date: 16.OCT.2017 22:26:58

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 16.OCT.2017 22:18:27

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 16.OCT.2017 22:26:36

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 6GHz~9GHz




Date: 16.OCT.2017 22:57:28

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 6GHz~9GHz




Date: 16.OCT.2017 23:07:57

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 16.OCT.2017 22:58:20

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 16.OCT.2017 23:07:10

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 6GHz~9GHz




Date: 16.OCT.2017 23:21:42

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 6GHz~9GHz




Date: 16.OCT.2017 23:29:36

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 16.OCT.2017 23:22:13

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 16.OCT.2017 23:29:06

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 19:38:06

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 20:00:03

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 19:39:06

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 20:00:59

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 6GHz~9GHz




Date: 16.OCT.2017 23:41:48

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 6GHz~9GHz




Date: 16.OCT.2017 23:54:22

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 16.OCT.2017 23:42:45

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 16.OCT.2017 23:53:56

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 00:56:41

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 01:03:17

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 00:56:23

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 01:03:36

Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 01:16:01

Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 01:23:41

Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 01:15:37

Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 01:23:54

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 20:28:54

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 20:44:53

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 17.OCT.2017 20:29:46

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 17.OCT.2017 20:45:52

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 18:01:51

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 19:34:00


Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 19:46:01

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 19:57:00

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 19:46:20

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 19:56:34

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 20:12:27

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 20:25:39

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 20:12:45

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 20:25:23

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 6GHz~9GHz




Date: 13.OCT.2017 01:24:59

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 6GHz~9GHz




Date: 13.OCT.2017 01:33:28

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 13.OCT.2017 01:25:17

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 13.OCT.2017 01:33:45

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:25:59

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 21:36:54

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:26:14

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 21:37:24

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:42:05

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 21:51:24

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:42:24

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 21:51:04

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:56:21

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 22:04:23

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 12.OCT.2017 21:56:42

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 12.OCT.2017 22:04:05

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 6GHz~9GHz




Date: 13.OCT.2017 01:25:56

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 6GHz~9GHz




Date: 13.OCT.2017 01:27:18

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 13.OCT.2017 01:26:19

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 13.OCT.2017 01:26:57

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 9GHz~18GHz




Date: 16.OCT.2017 22:19:23

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 9GHz~18GHz




Date: 16.OCT.2017 22:25:46

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 16.OCT.2017 22:19:41

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 16.OCT.2017 22:25:18

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 16.OCT.2017 22:59:18

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 16.OCT.2017 23:05:42

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 16.OCT.2017 22:59:50

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 16.OCT.2017 23:04:32

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 9GHz~18GHz



Date: 16.OCT.2017 23:22:59

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 9GHz~18GHz



Date: 16.OCT.2017 23:28:06