

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 1 / 6GHz~9GHz




Date: 22 JAN 2018 23:58:34

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 2 / 6GHz~9GHz




Date: 23 JAN 2018 00:08:13

Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 22. JAN.2018 23:58:13

Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 23. JAN.2018 00:08:30

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 1 / 9GHz~18GHz




Date: 18. JAN.2018 21:13:18

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 2 / 9GHz~18GHz




Date: 18. JAN.2018 20:48:48

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 18. JAN.2018 21:13:33

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 18. JAN.2018 20:49:10

Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 1 / 9GHz~18GHz




Date: 18. JAN.2018 21:09:50

Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 2 / 9GHz~18GHz




Date: 18. JAN.2018 21:08:36

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 18. JAN.2018 21:09:34

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 18. JAN.2018 21:08:54

Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 1 / 9GHz~18GHz




Date: 18. JAN.2018 19:01:58

Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 2 / 9GHz~18GHz




Date: 18. JAN.2018 19:07:32

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 18. JAN. 2018 19:02:21

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 18. JAN. 2018 19:07:13

Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 1 / 9GHz~18GHz




Date: 18. JAN.2018 21:19:00

Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 2 / 9GHz~18GHz




Date: 18. JAN.2018 21:20:20

Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 18. JAN.2018 21:18:34

Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 18. JAN.2018 21:20:41

Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 1 / 9GHz~18GHz




Date: 18. JAN.2018 21:29:46

Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 2 / 9GHz~18GHz




Date: 18. JAN.2018 21:25:31

Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 18. JAN.2018 21:30:00

Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 18. JAN.2018 21:25:15

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 1 / 9GHz~18GHz




Date: 18. JAN.2018 21:45:58

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 2 / 9GHz~18GHz




Date: 18. JAN.2018 21:46:34

Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 18 JAN 2018 21:37:46

Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 18 JAN 2018 21:46:49

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 1 / 18GHz~40GHz




Date: 18. JAN.2018 21:14:23

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 2 / 18GHz~40GHz




Date: 18. JAN.2018 20:50:16

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 18. JAN.2018 21:13:52

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 18. JAN.2018 20:49:40

Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 1 / 18GHz~40GHz




Date: 18. JAN.2018 21:06:32

Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 2 / 18GHz~40GHz




Date: 18. JAN.2018 21:08:13

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 18. JAN.2018 21:06:51

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 18. JAN.2018 21:07:41

Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 1 / 18GHz~40GHz




Date: 18. JAN.2018 19:03:21

Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 2 / 18GHz~40GHz




Date: 18. JAN.2018 19:06:25

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 18. JAN. 2018 19:02:46

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 18. JAN. 2018 19:06:41

Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 1 / 18GHz~40GHz




Date: 18. JAN.2018 21:17:50

Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 2 / 18GHz~40GHz




Date: 18. JAN.2018 21:21:37

Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 18 JAN 2018 21:18:08

Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 18 JAN 2018 21:21:04

Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 1 / 18GHz~40GHz




Date: 18. JAN.2018 21:31:04

Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 2 / 18GHz~40GHz




Date: 18. JAN.2018 21:23:23

Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 18. JAN.2018 21:30:25

Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 18. JAN.2018 21:23:41

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 1 / 18GHz~40GHz




Date: 18. JAN.2018 21:35:30

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 2 / 18GHz~40GHz




Date: 18. JAN.2018 21:47:34

Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 18. JAN.2018 21:35:53


Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 18. JAN.2018 21:47:05


For Antenna 2:

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 1 / 1GHz~3GHz




Date: 19. JAN.2018 15:48:07

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 2 / 1GHz~3GHz




Date: 19. JAN.2018 15:38:56

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 19. JAN.2018 15:48:23

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 19. JAN.2018 15:39:55

Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 1 / 1GHz~3GHz




Date: 19. JAN.2018 16:10:11

Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 2 / 1GHz~3GHz




Date: 19. JAN.2018 16:55:27


Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 1 / 1GHz~3GHz




Date: 19. JAN.2018 17:01:19

Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 2 / 1GHz~3GHz




Date: 19. JAN.2018 17:57:03

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 19. JAN.2018 17:01:58

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 19. JAN.2018 17:57:28

Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 1 / 1GHz~3GHz




Date: 19. JAN.2018 19:50:19

Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 2 / 1GHz~3GHz




Date: 19. JAN.2018 19:15:39

Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 19. JAN.2018 19:49:52

Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 19. JAN.2018 19:16:20

Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 1 / 1GHz~3GHz




Date: 19. JAN.2018 20:03:08

Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 2 / 1GHz~3GHz




Date: 19. JAN.2018 20:13:16

Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 19. JAN. 2018 20:03:24

Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 19. JAN. 2018 20:13:04

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 1 / 1GHz~3GHz




Date: 19. JAN.2018 20:55:09

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 2 / 1GHz~3GHz




Date: 19. JAN.2018 20:22:44

Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 19. JAN.2018 20:55:34

Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 19. JAN.2018 20:23:11

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 1 / 3GHz~6GHz




Date: 19. JAN. 2018 15:29:04

Plot on Configuration QPSK, 5M / 5730 MHz / Average / Port 2 / 3GHz~6GHz




Date: 19. JAN. 2018 15:34:31

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 19. JAN. 2018 15:29:44

Plot on Configuration QPSK, 5M / 5730 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 19. JAN. 2018 15:35:03

Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 1 / 3GHz~6GHz




Date: 19. JAN. 2018 16:22:16

Plot on Configuration QPSK, 5M / 5785 MHz / Average / Port 2 / 3GHz~6GHz




Date: 19. JAN. 2018 16:52:05

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 19. JAN. 2018 16:24:38

Plot on Configuration QPSK, 5M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 19. JAN. 2018 16:53:12

Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 1 / 3GHz~6GHz




Date: 19. JAN.2018 17:07:51

Plot on Configuration QPSK, 5M / 5845 MHz / Average / Port 2 / 3GHz~6GHz




Date: 19. JAN.2018 17:54:41

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 19. JAN. 2018 17:09:01

Plot on Configuration QPSK, 5M / 5845 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 19. JAN. 2018 17:55:40

Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 1 / 3GHz~6GHz




Date: 19. JAN.2018 19:39:23

Plot on Configuration QPSK, 40M / 5745 MHz / Average / Port 2 / 3GHz~6GHz




Date: 19. JAN.2018 19:40:28

Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 19. JAN.2018 19:38:48

Plot on Configuration QPSK, 40M / 5745 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 19. JAN.2018 19:41:18

Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 1 / 3GHz~6GHz




Date: 19. JAN.2018 20:08:48

Plot on Configuration QPSK, 40M / 5785 MHz / Average / Port 2 / 3GHz~6GHz




Date: 19. JAN.2018 20:10:53

Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 19. JAN.2018 20:08:21

Plot on Configuration QPSK, 40M / 5785 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 19. JAN.2018 20:10:02

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 1 / 3GHz~6GHz




Date: 19. JAN.2018 20:37:23

Plot on Configuration QPSK, 40M / 5830 MHz / Average / Port 2 / 3GHz~6GHz



Date: 19. JAN.2018 20:29:58

Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5830 MHz / Peak / Port 2 / 3GHz~6GHz

