



Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 21:33:44

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 21:41:15

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 21:34:32

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 21:42:16

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 16:59:52

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 17:16:38



Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 17:51:31

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 17:56:40

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 17:52:26

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 17:57:27

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 19:05:48

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 19:08:42



Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 19:32:53

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 19:35:44

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 19:33:53

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 19:36:52

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 20:01:04

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 20:04:05

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 20:01:53

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 20:05:00

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 20:39:06

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 20:42:10

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 /18GHz~40GHz




Date: 24.JAN.2018 20:39:51

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 20:42:48

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 21:07:40

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 21:10:32

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 21:08:53

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 21:11:19

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 18GHz~40GHz




Date: 24.JAN.2018 21:36:06

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 18GHz~40GHz




Date: 24.JAN.2018 21:38:58



Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 02:12:46

Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 02:18:26

Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 02:13:06

Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 02:18:14

Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 02:27:29

Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 02:21:51

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 02:27:17

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 02:22:08


Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 10:23:26

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 10:53:55

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 02:07:42

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 01:54:45

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 02:07:31

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 01:55:13

Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 03:11:11

Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 03:04:11

Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 03:10:48

Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 03:04:29

Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 03:27:39

Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 03:35:41

Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 03:27:56

Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 03:35:29

Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 03:55:48

Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 03:49:17

Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 03:55:38

Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 03:49:36

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 01:39:29

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 01:48:59

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 1 / 1GHz~3GHz



Date: 24.JAN.2018 01:39:41

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 2 / 1GHz~3GHz



Date: 24.JAN.2018 01:48:47


Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 24.JAN.2018 02:33:46

Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 02:35:41

Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 02:26:29

Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 02:23:28

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 02:26:09

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 02:23:55

Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 10:24:53

Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 10:50:03

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 10:27:12

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 10:51:16

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 02:05:56

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 02:01:28

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 1 / 3GHz~6GHz



Date: 24.JAN.2018 02:07:06

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 01:57:01

Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 03:11:57

Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 03:05:09

Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 24.JAN.2018 03:11:34

Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 24.JAN.2018 03:05:47

Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 03:29:20

Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 03:34:48

Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 03:29:43

Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 03:34:24

Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 03:54:46

Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 03:50:39


Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5700MHz / Peak / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 01:44:48

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 2 / 3GHz~6GHz



Date: 24.JAN.2018 01:47:55

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 2 / 3GHz~6GHz

