



Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 19:32:06

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 19:42:43

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 19:32:53

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 19:44:42

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 19:48:35

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 20:32:31

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 19:49:28

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 20:33:25

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 20:50:41

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 20:35:32

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 20:52:01

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 20:36:48

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 20:54:43

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 21:07:55

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 20:55:30

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 21:08:50


Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 21:18:19

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 21:29:17

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 21:33:28

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 21:44:08

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 21:34:13

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 21:45:17

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 21:47:57

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 1GHz~3GHz




Date: 9.FEB.2018 22:00:47

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 1GHz~3GHz




Date: 9.FEB.2018 21:48:34

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 1GHz~3GHz



Date: 9.FEB.2018 22:01:23

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 1 / 3GHz~6GHz




Date: 9.FEB.2018 19:16:29

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 2 / 3GHz~6GHz




Date: 9.FEB.2018 19:25:14

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 9.FEB.2018 19:17:21

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 9.FEB.2018 19:26:09

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 1 / 3GHz~6GHz




Date: 9.FEB.2018 19:34:13

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 2 / 3GHz~6GHz




Date: 9.FEB.2018 19:41:00

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 3GHz~6GHz




Date: 9.FEB.2018 19:50:46

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 3GHz~6GHz




Date: 9.FEB.2018 20:26:51

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 9 FEB. 2018 19:51:55

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 9 FEB. 2018 20:29:33

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 3GHz~6GHz




Date: 9.FEB.2018 20:48:15

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 3GHz~6GHz




Date: 9.FEB.2018 20:38:08

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 3GHz~6GHz



Date: 9.FEB.2018 20:49:42

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 3GHz~6GHz



Date: 9.FEB.2018 20:39:59


Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 3GHz~6GHz




Date: 9.FEB.2018 21:19:28

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 3GHz~6GHz




Date: 9.FEB.2018 21:26:52

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 9.FEB.2018 21:21:00

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 9.FEB.2018 21:27:41

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 3GHz~6GHz




Date: 9.FEB.2018 21:35:04

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 3GHz~6GHz




Date: 9.FEB.2018 21:42:05

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 3GHz~6GHz




Date: 9.FEB.2018 21:50:04

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 3GHz~6GHz




Date: 9.FEB.2018 21:57:57

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 3GHz~6GHz




Date: 9.FEB.2018 21:51:45

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 3GHz~6GHz




Date: 9.FEB.2018 21:59:11

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 19:18:35

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 2 / 1 6GHz~9GHz




Date: 9.FEB.2018 19:21:43

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 19:20:29

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 19:22:33

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 19:35:55

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 19:39:09

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 19:37:15

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 19:39:56

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 19:58:15

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 20:00:57

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 19:58:57

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 20:01:48

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 20:45:57

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 20:40:50

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 20:46:44

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Chnnel) / Peak / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 20:41:42

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 20:59:59

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 21:03:00

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 21:00:55

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 21:03:42

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 21:22:06

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 21:24:56

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 21:23:20

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 21:25:44

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 21:37:12

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 21:40:15

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 21:38:55

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 21:41:04

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 21:52:36

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 21:54:47

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 6GHz~9GHz




Date: 9.FEB.2018 21:53:13

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 6GHz~9GHz




Date: 9.FEB.2018 21:56:41


Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 10.FEB.2018 09:21:15

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:22:16

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:24:16

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:23:25

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 10.FEB.2018 09:24:39

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 10.FEB.2018 09:23:36