

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:25:38

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:26:28


Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:28:59

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:28:02

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:29:15

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:28:15

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:30:28

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:31:30

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:30:40

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 10.FEB.2018 09:31:56

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:34:24

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:33:01

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:34:40

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:33:47

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:35:35

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:36:41

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:35:43

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:36:58

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:39:14

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:38:15

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:39:32

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:38:46

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:41:35

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:42:55

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:41:48

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:43:08

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:54:15

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:53:19

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:54:25

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:53:28

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:55:33

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:56:52

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:55:45

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:57:04

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:59:44

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:58:38

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:59:57

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:58:57


Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:02:49

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:04:16


Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:06:58

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:05:34

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:07:53

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:08:45


Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:10:41

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:09:56


Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:27:13

Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:23:03

Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 10.FEB.2018 11:28:56

Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 10.FEB.2018 11:26:37


Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:40:59

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:44:09

Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:50:05

Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:47:36

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:50:19

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:48:14

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:54:13

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:58:30

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:54:27

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:58:40

Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:07:57

Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:04:39

Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:08:11

Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:05:05

Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:12:11

Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:14:44

Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:12:26

Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:15:08

Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:32:16

Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:29:12

Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:32:29

Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:29:22

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:35:50

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:40:14

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 1 / 1GHz~3GHz



Date: 10.FEB.2018 12:36:00

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 2 / 1GHz~3GHz



Date: 10.FEB.2018 12:40:26

Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 1 / 3GHz~6GHz




Date: 10.FEB.2018 11:27:29

Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 2 / 3GHz~6GHz




Date: 10.FEB.2018 11:23:38

Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 1 / 3GHz~6GHz




Date: 10.FEB.2018 11:41:35

Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 2 / 3GHz~6GHz




Date: 10.FEB.2018 11:43:12

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 10.FEB.2018 11:41:50

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 10.FEB.2018 11:43:21


Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 2 / 3GHz~6GHz

