

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 1 / 3GHz~6GHz




Date: 10.FEB.2018 11:56:02

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 2 / 3GHz~6GHz




Date: 10.FEB.2018 11:57:58

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 1 / 3GHz~6GHz




Date: 10.FEB.2018 11:56:13

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 2 / 3GHz~6GHz



Date: 10.FEB.2018 11:58:13

Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 1 / 3GHz~6GHz




Date: 10.FEB.2018 12:08:35

Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 2 / 3GHz~6GHz




Date: 10.FEB.2018 12:05:56

Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5700MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 11:27:48

Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 2 / 1 6GHz~9GHz




Date: 10.FEB.2018 11:23:57


Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 11:42:16

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 10.FEB.2018 11:42:54

Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 11:51:34

Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 2 / 6GHz~9GHz




Date: 10.FEB.2018 11:49:21

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 11:51:45

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 10.FEB.2018 11:49:31


Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 11:56:42


Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 2 / 6GHz~9GHz



Date: 10.FEB.2018 11:57:25




Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 12:09:24

Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 10.FEB.2018 12:06:56

Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 12:13:57

Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 2 / 6GHz~9GHz




Date: 10.FEB.2018 12:16:11

Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 12:14:05

Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 10.FEB.2018 12:16:26

Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 12:31:08

Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 2 / 6GHz~9GHz




Date: 10.FEB.2018 12:30:26

Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 12:31:19

Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 10.FEB.2018 12:30:35

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 12:37:21

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 2 / 6GHz~9GHz




Date: 10.FEB.2018 12:38:18

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 1 / 6GHz~9GHz




Date: 10.FEB.2018 12:37:36

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 2 / 6GHz~9GHz




Date: 10.FEB.2018 12:38:45


Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 10:53:25

Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 10:54:12

Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 10:55:47

Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 10:55:03

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 10.FEB.2018 10:55:55

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 10:55:10

Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 10:56:46

Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 10:57:34

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 10:56:55

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 10.FEB.2018 10:57:41

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 10:59:15

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 10:58:32

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 10:59:29

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 10:58:41


Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 11:01:49

Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 11:02:37


Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 11:04:38

Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 11:03:41


Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 11:05:30

Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 11:06:16

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 11:08:02

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 11:07:09

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 11:08:14

Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 11:07:17

Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:13:48

Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:14:34

Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:13:57

Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:14:41

Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:17:26

Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:16:31

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:17:37

Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:16:41

Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:26:56

Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:27:51

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:27:04

Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:28:03

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:30:16

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 2 / 18GHz~40GHz



Date: 10.FEB.2018 10:29:06

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 1 / 18GHz~40GHz



Date: 10.FEB.2018 10:30:23

Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 2 / 18GHz~40GHz