



Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 20:54:33

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 21:20:14

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 20:55:29

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 24.JAN.2018 21:21:14

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 1GHz~3GHz




Date: 24.JAN.2018 21:26:14

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 1GHz~3GHz




Date: 24.JAN.2018 21:55:51

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 1GHz~3GHz



Date: 24.JAN.2018 21:27:50

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 1GHz~3GHz



Date: 24.JAN.2018 21:56:54

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 16:45:31

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 17:27:25

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 24.JAN.2018 16:46:37

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 24.JAN.2018 17:28:24

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 17:40:20

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 18:05:59

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 24.JAN.2018 17:42:54

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 24.JAN.2018 18:06:51


Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 24.JAN.2018 18:58:15

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 24.JAN.2018 19:17:03

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 19:24:49

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 19:44:45

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 3GHz~6GHz



Date: 24.JAN.2018 19:25:56

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 3GHz~6GHz



Date: 24.JAN.2018 19:46:15


Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 24.JAN.2018 19:54:50

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 24.JAN.2018 20:19:52


Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 24.JAN.2018 20:57:37

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 24.JAN.2018 21:18:47

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 21:29:02

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 21:49:13

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 3GHz~6GHz




Date: 24.JAN.2018 21:30:34

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 3GHz~6GHz




Date: 24.JAN.2018 21:52:10

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 16:48:01

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 2 / 1 6GHz~9GHz




Date: 24.JAN.2018 17:24:28

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 16:48:45

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 17:25:28

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 17:45:40

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 18:03:13

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 17:46:38

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 18:03:59

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 18:59:37

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 19:13:22

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 19:00:48

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 19:14:21

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 19:27:23

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 19:42:25

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 19:27:56

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 19:43:18

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 19:55:39

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 20:16:08

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 19:56:27

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 20:17:27

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 20:32:53

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 20:46:34

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 20:33:42

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 20:47:24

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 20:58:31

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 21:14:45

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 24.JAN.2018 21:02:06

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 21:15:47

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 21:31:51

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 21:43:08

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 6GHz~9GHz




Date: 24.JAN.2018 21:32:34

Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 6GHz~9GHz




Date: 24.JAN.2018 21:43:50

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 16:54:28

Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 17:19:55

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 16:57:13

Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 17:20:55

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 17:49:28

Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 17:59:33

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 17:50:11

Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 18:00:52

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 19:02:50

Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 19:10:23

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 19:04:23

Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 19:11:00

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 19:30:13

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 19:38:34

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 19:31:06

Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 19:39:36

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 19:58:45

Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 20:06:04

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 19:59:32

Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 20:07:29

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 20:36:18

Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 20:43:41

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 20:37:28

Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 20:44:47

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 9GHz~18GHz




Date: 24.JAN.2018 21:04:45

Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 9GHz~18GHz




Date: 24.JAN.2018 21:12:23

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 24.JAN.2018 21:05:55

Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 24.JAN.2018 21:13:00