




























TOSHIBA OW6189
TAMAWAN 13249A E
58NVG1S3HTA00










EDA SN: NR3020FX



SKhynix
H5102G63DFR
H9C 325V
H9C 325V

NA3020FX

Z0Z

0202

PG16
F1788
-17MV
132882

FZCE

1.0

LF

KL3

FZCE

ETB9

0020

101

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

ME10

SKhynix
H5TQ2G630FA
H9C 326V
• NwLE56B3

NR3020FX

MAIN BOARD_VIKO_20131126

36A24ZW GI
962B ZCZ

AM352BZCZ100


PLC16
F1789
-1/MV3
132382

FZOE

NS2C

LF

E10061224
1843





<http://www.seagate.com>



S/N: S2YFJ9BDB01912

Model : ST1000LM024
HDD P/N : HN-M101MBB/SBZ
LBA 1,953,525,168 1000.0GB

WARRANTY VOID IF REMOVED

REV. A
FW : 2AR20003



Momentus®

SAMSUNG SPINPOINT

HARD DISK DRIVE RATED : DC+5V --- 0.85A

WARNING : SENSITIVE PARTS INSIDE. FAILURE MAY OCCUR IF SUBJECT TO EXCESSIVE SHOCK, TOUCHING THE CIRCUITRY MAY CAUSE DAMAGE. REMOVING THIS COVER WILL VOID ANY AND ALL WARRANTIES.



Product of CHINA
HDD Mfg by Seagate Technology LLC
DOM: 11/2013
Site: DGT

DO NOT COVER THIS SIDE

European Regulatory Address:
Seagate Technology Int'l
Koolhofvenlaan 1,
1119 NB Schiphol-Rijk,
The Netherlands

P/N : E0373-G14A-B15U6

