

B38 , Normal

Mode	Value (dBm)	Limit	Result
5MHz_Low_QPSK_1@0	-34.31	See Graphs	Pass
5MHz_Low_QPSK_25@0	-33.10	See Graphs	Pass
5MHz_Middle_QPSK_1@0	-33.68	See Graphs	Pass
5MHz_Middle_QPSK_25@0	-33.95	See Graphs	Pass
5MHz_High_QPSK_1@0	-33.27	See Graphs	Pass
5MHz_High_QPSK_25@0	-33.52	See Graphs	Pass
10MHz_Low_QPSK_1@0	-33.56	See Graphs	Pass
10MHz_Low_QPSK_50@0	-32.96	See Graphs	Pass
10MHz_Middle_QPSK_1@0	-32.71	See Graphs	Pass
10MHz_Middle_QPSK_50@0	-33.30	See Graphs	Pass
10MHz_High_QPSK_1@0	-33.69	See Graphs	Pass
10MHz_High_QPSK_50@0	-33.41	See Graphs	Pass
15MHz_Low_QPSK_1@0	-33.26	See Graphs	Pass
15MHz_Low_QPSK_75@0	-32.66	See Graphs	Pass
15MHz_Middle_QPSK_1@0	-33.88	See Graphs	Pass
15MHz_Middle_QPSK_75@0	-33.53	See Graphs	Pass
15MHz_High_QPSK_1@0	-32.40	See Graphs	Pass
15MHz_High_QPSK_75@0	-33.47	See Graphs	Pass
20MHz_Low_QPSK_1@0	-33.84	See Graphs	Pass
20MHz_Low_QPSK_100@0	-32.73	See Graphs	Pass
20MHz_Middle_QPSK_1@0	-33.52	See Graphs	Pass
20MHz_Middle_QPSK_100@0	-32.72	See Graphs	Pass
20MHz_High_QPSK_1@0	-33.94	See Graphs	Pass
20MHz_High_QPSK_100@0	-33.83	See Graphs	Pass

B4 , Normal


Mode	Value (dBm)	Limit	Result
1.4MHz_Low_QPSK_1@0	-23.29	See Graphs	Pass
1.4MHz_Low_QPSK_6@0	-23.67	See Graphs	Pass
1.4MHz_Middle_QPSK_1@0	-24.16	See Graphs	Pass
1.4MHz_Middle_QPSK_6@0	-23.60	See Graphs	Pass
1.4MHz_High_QPSK_1@0	-22.89	See Graphs	Pass
1.4MHz_High_QPSK_6@0	-22.87	See Graphs	Pass
3MHz_Low_QPSK_1@0	-23.92	See Graphs	Pass
3MHz_Low_QPSK_15@0	-24.32	See Graphs	Pass
3MHz_Middle_QPSK_1@0	-23.89	See Graphs	Pass
3MHz_Middle_QPSK_15@0	-24.31	See Graphs	Pass
3MHz_High_QPSK_1@0	-23.27	See Graphs	Pass
3MHz_High_QPSK_15@0	-24.00	See Graphs	Pass
5MHz_Low_QPSK_1@0	-22.59	See Graphs	Pass
5MHz_Low_QPSK_25@0	-23.19	See Graphs	Pass
5MHz_Middle_QPSK_1@0	-22.93	See Graphs	Pass
5MHz_Middle_QPSK_25@0	-23.32	See Graphs	Pass
5MHz_High_QPSK_1@0	-23.44	See Graphs	Pass
5MHz_High_QPSK_25@0	-23.81	See Graphs	Pass
10MHz_Low_QPSK_1@0	-23.75	See Graphs	Pass
10MHz_Low_QPSK_50@0	-23.57	See Graphs	Pass
10MHz_Middle_QPSK_1@0	-23.04	See Graphs	Pass
10MHz_Middle_QPSK_50@0	-23.72	See Graphs	Pass
10MHz_High_QPSK_1@0	-22.75	See Graphs	Pass
10MHz_High_QPSK_50@0	-23.54	See Graphs	Pass
15MHz_Low_QPSK_1@0	-22.92	See Graphs	Pass
15MHz_Low_QPSK_75@0	-23.72	See Graphs	Pass
15MHz_Middle_QPSK_1@0	-23.59	See Graphs	Pass
15MHz_Middle_QPSK_75@0	-23.47	See Graphs	Pass
15MHz_High_QPSK_1@0	-23.98	See Graphs	Pass
15MHz_High_QPSK_75@0	-23.43	See Graphs	Pass
20MHz_Low_QPSK_1@0	-23.67	See Graphs	Pass
20MHz_Low_QPSK_100@0	-23.31	See Graphs	Pass
20MHz_Middle_QPSK_1@0	-23.90	See Graphs	Pass
20MHz_Middle_QPSK_100@0	-24.35	See Graphs	Pass
20MHz_High_QPSK_1@0	-23.46	See Graphs	Pass
20MHz_High_QPSK_100@0	-24.05	See Graphs	Pass

B7 , Normal

Mode	Value (dBm)	Limit	Result
5MHz_Low_QPSK_1@0	-33.88	See Graphs	Pass
5MHz_Low_QPSK_25@0	-33.37	See Graphs	Pass
5MHz_Middle_QPSK_1@0	-34.18	See Graphs	Pass
5MHz_Middle_QPSK_25@0	-33.09	See Graphs	Pass
5MHz_High_QPSK_1@0	-33.53	See Graphs	Pass
5MHz_High_QPSK_25@0	-33.50	See Graphs	Pass
10MHz_Low_QPSK_1@0	-33.35	See Graphs	Pass
10MHz_Low_QPSK_50@0	-33.80	See Graphs	Pass
10MHz_Middle_QPSK_1@0	-33.73	See Graphs	Pass
10MHz_Middle_QPSK_50@0	-33.54	See Graphs	Pass
10MHz_High_QPSK_1@0	-33.75	See Graphs	Pass
10MHz_High_QPSK_50@0	-33.24	See Graphs	Pass
15MHz_Low_QPSK_1@0	-33.70	See Graphs	Pass
15MHz_Low_QPSK_75@0	-34.19	See Graphs	Pass
15MHz_Middle_QPSK_1@0	-34.33	See Graphs	Pass
15MHz_Middle_QPSK_75@0	-32.35	See Graphs	Pass
15MHz_High_QPSK_1@0	-33.50	See Graphs	Pass
15MHz_High_QPSK_75@0	-33.96	See Graphs	Pass
20MHz_Low_QPSK_1@0	-33.45	See Graphs	Pass
20MHz_Low_QPSK_100@0	-33.67	See Graphs	Pass
20MHz_Middle_QPSK_1@0	-32.55	See Graphs	Pass
20MHz_Middle_QPSK_100@0	-33.01	See Graphs	Pass
20MHz_High_QPSK_1@0	-34.12	See Graphs	Pass
20MHz_High_QPSK_100@0	-34.21	See Graphs	Pass


B38 , Normal

5MHz_Low_QPSK_1@0 -34.31 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:39:10

5MHz_Low_QPSK_25@0 -33.10 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:39:33

5MHz_Mid_QPSK_1@0 -33.68 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:39:57

5MHz_Mid_QPSK_25@0 -33.95 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:40:20

5MHz_High_QPSK_1@0 -33.27 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:40:43

5MHz_High_QPSK_25@0 -33.52 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:41:07

10MHz_Low_QPSK_1@0 -33.56 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:42:01

10MHz_Low_QPSK_50@0 -32.96 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:42:24

10MHz_Mid_QPSK_1@0 -32.71 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:42:48

10MHz_Mid_QPSK_50@0 -33.30 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:43:11

10MHz_High_QPSK_1@0 -33.69 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:43:35

10MHz_High_QPSK_50@0 -33.41 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 17:44:01

15MHz_Low_QPSK_1@0 -33.26 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 17:44:54

15MHz_Low_QPSK_75@0 -32.66 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 17:45:18

15MHz_Mid_QPSK_1@0 -33.88 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 17:45:42

15MHz_Mid_QPSK_75@0 -33.53 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 17:46:05

15MHz_High_QPSK_1@0 -32.40 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 17:46:29

15MHz_High_QPSK_75@0 -33.47 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 17:46:53

20MHz_Low_QPSK_1@0 -33.84 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 18:24:51

20MHz_Low_QPSK_100@0 -32.73 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 18:25:15

20MHz_Mid_QPSK_1@0 -33.52 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 18:25:41

20MHz_Mid_QPSK_100@0 -32.72 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 18:26:06

20MHz_High_QPSK_1@0 -33.94 dBm



ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 18:26:31


20MHz_High_QPSK_100@0 -33.83 dBm



ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY 2024 18:26:56


B4 , Normal

1.4MHz_Low_QPSK_1@0 -23.29 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:36:08

1.4MHz_Low_QPSK_6@0 -23.67 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:36:24

1.4MHz_Mid_QPSK_1@0 -24.16 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:36:41

1.4MHz_Mid_QPSK_6@0 -23.60 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:36:58

1.4MHz_High_QPSK_1@0 -22.89 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:37:15

1.4MHz_High_QPSK_6@0 -22.87 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:37:31

3MHz_Low_QPSK_1@0 -23.92 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:38:18

3MHz_Low_QPSK_15@0 -24.32 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:38:35

3MHz_Mid_QPSK_1@0 -23.89 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:38:55

3MHz_Mid_QPSK_15@0 -24.31 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:39:12

3MHz_High_QPSK_1@0 -23.27 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:39:30

3MHz_High_QPSK_15@0 -24.00 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:39:50

5MHz_Low_QPSK_1@0 -22.59 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:40:36

5MHz_Low_QPSK_25@0 -23.19 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:40:54

5MHz_Mid_QPSK_1@0 -22.93 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:41:11

5MHz_Mid_QPSK_25@0 -23.32 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:41:30

5MHz_High_QPSK_1@0 -23.44 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:41:47

5MHz_High_QPSK_25@0 -23.81 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:42:04

10MHz_Low_QPSK_1@0 -23.75 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:42:53

10MHz_Low_QPSK_50@0 -23.57 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:43:10

10MHz_Mid_QPSK_1@0 -23.04 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:43:27

10MHz_Mid_QPSK_50@0 -23.72 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:43:44

10MHz_High_QPSK_1@0 -22.75 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:44:01

10MHz_High_QPSK_50@0 -23.54 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:44:18

15MHz_Low_QPSK_1@0 -22.92 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:45:08

15MHz_Low_QPSK_75@0 -23.72 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:45:29

15MHz_Mid_QPSK_1@0 -23.59 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:45:50

15MHz_Mid_QPSK_75@0 -23.47 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:46:07

15MHz_High_QPSK_1@0 -23.98 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:46:24

15MHz_High_QPSK_75@0 -23.43 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24 MAY.2024 15:46:41

20MHz_Low_QPSK_1@0 -23.67 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:47:27

20MHz_Low_QPSK_100@0 -23.31 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:47:44

20MHz_Mid_QPSK_1@0 -23.90 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:48:01

20MHz_Mid_QPSK_100@0 -24.35 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:48:19

20MHz_High_QPSK_1@0 -23.46 dBm



ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:48:36


20MHz_High_QPSK_100@0 -24.05 dBm



ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 15:48:53


B7 , Normal

5MHz_Low_QPSK_1@0 -33.88 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:03:18

5MHz_Low_QPSK_25@0 -33.37 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:03:38

5MHz_Mid_QPSK_1@0 -34.18 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:04:00

5MHz_Mid_QPSK_25@0 -33.09 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:04:24

5MHz_High_QPSK_1@0 -33.53 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:04:46

5MHz_High_QPSK_25@0 -33.50 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:05:07

10MHz_Low_QPSK_1@0 -33.35 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:05:58

10MHz_Low_QPSK_50@0 -33.80 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:06:18

10MHz_Mid_QPSK_1@0 -33.73 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:06:39

10MHz_Mid_QPSK_50@0 -33.54 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:07:00

10MHz_High_QPSK_1@0 -33.75 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:07:20

10MHz_High_QPSK_50@0 -33.24 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:07:40

15MHz_Low_QPSK_1@0 -33.70 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:08:29

15MHz_Low_QPSK_75@0 -34.19 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:08:51

15MHz_Mid_QPSK_1@0 -34.33 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:09:12

15MHz_Mid_QPSK_75@0 -32.35 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:09:32

15MHz_High_QPSK_1@0 -33.50 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:09:53

15MHz_High_QPSK_75@0 -33.96 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:10:13

20MHz_Low_QPSK_1@0 -33.45 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:11:01

20MHz_Low_QPSK_100@0 -33.67 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:11:21

20MHz_Mid_QPSK_1@0 -32.55 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:11:42

20MHz_Mid_QPSK_100@0 -33.01 dBm




ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:12:02

20MHz_High_QPSK_1@0 -34.12 dBm



ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:12:22

20MHz_High_QPSK_100@0 -34.21 dBm



ProjectNo.:RKSA240319001 Tester:Loki Shi
Date: 24.MAY.2024 16:12:43