



20MHz_Low_QPSK_100@0

Occupied Bandwidth



26dB Bandwidth

ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:44:46ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:44:56

20MHz_Low_16QAM_100@0

Occupied Bandwidth



26dB Bandwidth

ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:45:25ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:45:35

20MHz_Middle_QPSK_100@0

Occupied Bandwidth


26dB Bandwidth

ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:46:05ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:46:16


20MHz_Middle_16QAM_100@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo: RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:46:47




ProjectNo: RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:46:58


20MHz_High_QPSK_100@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo: RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:47:29




ProjectNo: RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:47:41


20MHz_High_16QAM_100@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo: RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:48:12




ProjectNo: RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:48:24

B7 , Normal


5MHz_Low_QPSK_25@0

Occupied Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:10:15


26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:10:23


5MHz_Low_16QAM_25@0

Occupied Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:10:44


26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:10:52


5MHz_Middle_QPSK_25@0

Occupied Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:11:13

26dB Bandwidth




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:11:21


5MHz_Middle_16QAM_25@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:11:42




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:11:50


5MHz_High_QPSK_25@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:12:12




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:12:21


5MHz_High_16QAM_25@0

Occupied Bandwidth

26dB Bandwidth




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:12:43



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:12:52


10MHz_Low_QPSK_50@0

Occupied Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:13:46


26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:13:54


10MHz_Low_16QAM_50@0

Occupied Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:14:17


26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:14:25


10MHz_Middle_QPSK_50@0

Occupied Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:14:49

26dB Bandwidth




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:14:58


10MHz_Middle_16QAM_50@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:15:21




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:15:30


10MHz_High_QPSK_50@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:15:54




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:16:03


10MHz_High_16QAM_50@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:16:27





ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:16:36

15MHz_Low_QPSK_75@0

Occupied Bandwidth



26dB Bandwidth

ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:17:53ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:18:02

15MHz_Low_16QAM_75@0

Occupied Bandwidth



26dB Bandwidth

ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:18:27ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:18:36

15MHz_Middle_QPSK_75@0

Occupied Bandwidth


26dB Bandwidth

ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:19:00ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:19:10


15MHz_Middle_16QAM_75@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:19:35




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:19:45


15MHz_High_QPSK_75@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:20:10




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:20:19


15MHz_High_16QAM_75@0

Occupied Bandwidth

26dB Bandwidth




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:20:46




ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:20:56

20MHz_Low_QPSK_100@0

Occupied Bandwidth


ProjectNo. RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:21:53

26dB Bandwidth


ProjectNo. RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:22:03

20MHz_Low_16QAM_100@0

Occupied Bandwidth


ProjectNo. RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:22:30

26dB Bandwidth


ProjectNo. RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:22:40

20MHz_Middle_QPSK_100@0

Occupied Bandwidth


ProjectNo. RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:23:07

26dB Bandwidth

ProjectNo. RKSA240906001 Tester:Jason Lu
Date: 5 DEC 2024 15:23:17


20MHz_Middle_16QAM_100@0

Occupied Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:23:46


26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:23:56


20MHz_High_QPSK_100@0

Occupied Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:24:24


26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:24:34


20MHz_High_16QAM_100@0

Occupied Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:25:02

26dB Bandwidth



ProjectNo. RKSA240906001 Tester.Jason Lu
Date: 5 DEC 2024 15:25:12