







Mode:802.11ax HE20 Tone:242T Frequency:5955MHz
Ant:Chain0




Mode:802.11ax HE20 Tone:242T Frequency:6175MHz
Ant:Chain0




Mode:802.11ax HE20 Tone:242T Frequency:6415MHz
Ant:Chain0



Mode:802.11ax HE20 Tone:242T Frequency:5955MHz
Ant:Chain1




Mode:802.11ax HE20 Tone:242T Frequency:6175MHz
Ant:Chain1




Mode:802.11ax HE20 Tone:242T Frequency:6415MHz
Ant:Chain1


Test Mode: 802.11ax HE40







Test Mode: 802.11ax HE80



Test Mode: 802.11ax HE160



NOTE: For the Partial RU , The worst case is RU26, so it just shows the worst test plots in the report.
Test Mode: 802.11ax HE20



Test Mode: 802.11ax HE40

