16. External Photos

Overall Dimensions



This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Front View of the DUT

Rear View of the DUT

UL Verification Services Inc.
47173 BENICIA STREET, FREMONT, CA 94538, USA
TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031G
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

17. Antenna Dimensions & Separation Distances





This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

18. Setup Photos

18.1. Head RF Exposure Conditions

Left Touch



Left Tilt (15°)

UL Verification Services Inc.
47173 BENICIA STREET, FREMONT, CA 94538, USA
TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031G
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Right Touch



Right Tilt (15°)



UL Verification Services Inc. FORM NO: CCSUP4031G
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

18.2. Body-worn Accessory & Hotspot mode RF Exposure Conditions

Rear



Front



UL Verification Services Inc.
FORM NO: CCSUP4031G
47173 BENICIA STREET, FREMONT, CA 94538, USA
TEL: (510) 771-1000
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

18.3. Hotspot RF Exposure Conditions

Edge 1



Edge 2



UL Verification Services Inc.
FORM NO: CCSUP4031G
47173 BENICIA STREET, FREMONT, CA 94538, USA
TEL: (510) 771-1000
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Edge 3



Edge 4



END OF REPORT

UL Verification Services Inc.
47173 BENICIA STREET, FREMONT, CA 94538, USA
TEL: (510) 771-1000 FAX: (510) 661-0888
FORM NO: CCSUP4031G
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.