


3. Internal Photograph of EUT


Brand Name: LG; Model Name: LG-X220m




Brand Name: LG; Model Name: LG-X220m




Brand Name: LG; Model Name: LG-X220m




Brand Name: LG; Model Name: LG-X220m




Brand Name: LG; Model Name: LG-X220m




Brand Name: LG; Model Name: LG-X220m



Brand Name: LG; Model Name: LG-X220m



Brand Name: LG; Model Name: LG-X220m





Brand Name: LG; Model Name: LG-X220m




Page Number : 20 of 29
Report Issued Date : Mar. 03, 2016
Report Version : Rev. 01

Brand Name: LG; Model Name: LG-X220m



Brand Name: LG; Model Name: LG-X220m


Brand Name: LG; Model Name: LG-X220m



Brand Name: LG; Model Name: LG-X220m




Brand Name: LG; Model Name: LG-X220m



Brand Name: LG; Model Name: LG-X220m




Brand Name: LG; Model Name: LG-X220m





Brand Name: LG; Model Name: LG-X220m



Brand Name: LG; Model Name: LG-X220m

