


3. Photographs of Test

CE Testing Set-up



FCC ID: ZVZP42350FA3


IC ID: 9906A-P42350FA3

Report No. : E1/2014/70052

Page : 21 of 30

RE Testing Set-up

Below 1GHz





FCC ID: ZVZP42350FA3


IC ID: 9906A-P42350FA3

Report No. : E1/2014/70052

Page : 22 of 30

Above 1GHz





FCC ID: ZVZP42350FA3


IC ID: 9906A-P42350FA3

Report No. : E1/2014/70052

Page : 24 of 30



8G




FCC ID: ZVZP42350FA3

IC ID: 9906A-P42350FA3

Report No. : E1/2014/70052

Page : 25 of 30





IC ID: 9906A-P42350FA3

Report No. : E1/2014/70052

Page : 26 of 30

16G




FCC ID: ZVZP42350FA3

IC ID: 9906A-P42350FA3

Report No. : E1/2014/70052

Page : 27 of 30





IC ID: 9906A-P42350FA3

Report No. : E1/2014/70052

Page : 28 of 30

Interior





FCC ID: ZVZP42350FA3

IC ID: 9906A-P42350FA3

Report No. : E1/2014/70052

Page : 29 of 30





FCC ID: ZVZP42350FA3

IC ID: 9906A-P42350FA3

Report No. : E1/2014/70052

Page : 30 of 30



** End of Report **