



Dayton Audio

Wireless Speaker Kit with Subwoofer Output (M/N): XRA25

1. working voltage: DC 9V/0.2A.
2. modulation GFSK
3. 2.4GHz ISM Band
4. Low LBOM cost
5. Audio format 16bit , 48KHz sampling rate
6. Power ON/OFF pop noise reduction
7. Robust Packet error correction
8. Low power consumption
9. No RF induced audio noise
10. Ready to go reference system
11. S/N: -95dB

Main Function






Power button

The application diagram



DVD



Mp3

wired

Wireless Speaker Kit with Subwoofer Output

audio RF Receiver



FCC Certification Requirements

Caution: Any changes or modifications in construction of this device which are not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and
(2) This device must accept any interference received, including interference that may cause undesired operation.

The manufacturer is not responsible for any radio or TV interference caused by unauthorized modifications to this equipment. Such modifications could void the user's authority to operate the equipment.

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.