



INTERTEK TESTING SERVICE

Report No.: 15080865HKG-001

Equipment Photographs

Model : 1201682

(Internal)



FCC ID: ZY9-1201682


INTERTEK TESTING SERVICE

Report No.: 15080865HKG-001

Equipment Photographs

Model : 1201682

(Internal)



FCC ID: ZY9-1201682


INTERTEK TESTING SERVICE

Report No.: 15080865HKG-001

Equipment Photographs

Model : 1201682

(Internal)



FCC ID: ZY9-1201682



INTERTEK TESTING SERVICE

Report No.: 15080865HKG-001

Equipment Photographs

Model : 1201682

(Internal)



FCC ID: ZY9-1201682



INTERTEK TESTING SERVICE

Report No.: 15080865HKG-001

Equipment Photographs

Model : 1201682

(Internal)



FCC ID: ZY9-1201682


INTERTEK TESTING SERVICE

Report No.: 15080865HKG-001

Equipment Photographs

Model : 1201682

(Internal)



FCC ID: ZY9-1201682



INTERTEK TESTING SERVICE

Report No.: 15080865HKG-001

Equipment Photographs

Model : 1201682

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15080865HKG-001

Equipment Photographs

Model : 1201682

(Internal)



FCC ID: ZY9-1201682


INTERTEK TESTING SERVICE

Report No.: 15080865HKG-001

Equipment Photographs

Model : 1201682

(Internal)



FCC ID: ZY9-1201682