



報告編號 : 4790091528-EP

頁碼 : 1 of 34

報告發行日期 : 2022/1/11

External Photos
Group Pic 1





Outview: CBW390S5-AX5700 Pic 1



Outview: CBW390S5-AX5700 Pic 2





Outview: CBW390S5-AX5700 Pic 3



Outview: CBW390S5-AX5700 Pic 4





Outview: CBW390S5-AX5700 Pic 5




Outview: CBW390S5-AX5700 Pic 6



Accessory: MSS-V3500WR120-042A0-US Pic 1**Accessory: MSS-V3500WR120-042A0-US Pic 2**




Accessory: MSS-V3500WR120-042A0-US Pic 3



Accessory: MSS-V3500WR120-042A0-US Pic 4



Accessory: Lan Cable (Home+) PF01-C110 Pic 1



Accessory: Lan Cable (Home+) PF01-C110 Pic 2





Accessory: Lan Cable (Home+) PF01-C110 Pic 3



Accessory: Lan Cable (Generic) JY01-C066 Pic 1



Accessory: Lan Cable (Generic) JY01-C066 Pic 2





Accessory: Lan Cable (Generic) JY01-C066 Pic 3






Accessory: Coaxial Cable COMMSCOP 5781 (測試配件不隨同產品販售) Pic 1



Accessory: Coaxial Cable COMMSCOP 5781 (測試配件不隨同產品販售) Pic 2





Accessory: RJ-45 Cable Fastlink FL-61STU-04 (測試配件不隨同產品販售) Pic 1

此信號線材已固定於實驗場地，特以下形式證明線材相關資訊





Accessory: RJ-45 Cable Fastlink FL-61STU-04 (測試配件不隨同產品販售) Pic 2

此信號線材已固定於實驗場地，特以下形式證明線材相關資訊



Accessory: RJ-45 Cable OEM/AngNet UTP (測試配件不隨同產品販售) Pic 1



Accessory: RJ-45 Cable OEM/AngNet UTP (測試配件不隨同產品販售) Pic 2

