







NTNV-11N20SISO-Ant1-5600-5765~26000-See table below




NTNV-11N20SISO-Ant1-5700-30~5460-PASS








NTNV-11N20SISO-Ant1-5700-5765~26000-See table below




NTNV-11N40SISO-Ant1-5190-30~5141.6-See table below







NTNV-11N40SISO-Ant1-5190-5141.6~5150-See table below




NTNV-11N40SISO-Ant1-5190-5250~5251-PASS











NTNV-11N40SISO-Ant1-5230-5141.6~5150-PASS




NTNV-11N40SISO-Ant1-5230-5250~5251-See table below






NTNV-11N40SISO-Ant1-5230-5251~5270-See table below




NTNV-11N40SISO-Ant1-5230-5270~5278.4-See table below






NTNV-11N40SISO-Ant1-5230-5278.4~26000-See table below




NTNV-11N40SISO-Ant1-5270-30~5221.6-See table below






NTNV-11N40SISO-Ant1-5270-5221.6~5230-See table below




NTNV-11N40SISO-Ant1-5270-5230~5249-See table below







NTNV-11N40SISO-Ant1-5270-5249~5250-See table below





NTNV-11N40SISO-Ant1-5270-5350~5348.4-PASS













NTNV-11N40SISO-Ant1-5310-5348.4~26000-See table below




NTNV-11N40SISO-Ant1-5510-30~5460-See table below







NTNV-11N40SISO-Ant1-5510-5460~5470-See table below




NTNV-11N40SISO-Ant1-5510-5770~26000-PASS












NTNV-11N40SISO-Ant1-5670-5460~5470-PASS





NTNV-11N40SISO-Ant1-5670-5770~26000-PASS






















NTNV-11AC20SISO-Ant1-5200-5266.7~26000-PASS




NTNV-11AC20SISO-Ant1-5240-30~5142-PASS






NTNV-11AC20SISO-Ant1-5240-5142~5150-PASS




NTNV-11AC20SISO-Ant1-5240-5250~5250.2-See table below






NTNV-11AC20SISO-Ant1-5240-5250.2~5251-See table below




NTNV-11AC20SISO-Ant1-5240-5251~5260-See table below






NTNV-11AC20SISO-Ant1-5240-5260~5266.7-See table below




NTNV-11AC20SISO-Ant1-5240-5266.7~26000-See table below






NTNV-11AC20SISO-Ant1-5260-30~5233.3-See table below




NTNV-11AC20SISO-Ant1-5260-5233.3~5240-See table below






NTNV-11AC20SISO-Ant1-5260-5240~5249-See table below




NTNV-11AC20SISO-Ant1-5260-5249~5249.8-See table below






NTNV-11AC20SISO-Ant1-5260-5249.8~5250-See table below




NTNV-11AC20SISO-Ant1-5260-5350~26000-PASS







NTNV-11AC20SISO-Ant1-5280-30~5233.3-PASS





NTNV-11AC20SISO-Ant1-5280-5233.3~5240-See table below























NTNV-11AC20SISO-Ant1-5500-5745~5765-PASS





NTNV-11AC20SISO-Ant1-5500-5765~26000-PASS













NTNV-11AC20SISO-Ant1-5700-5745~5765-PASS




NTNV-11AC20SISO-Ant1-5700-5765~26000-See table below







NTNV-11AC40SISO-Ant1-5190-30~5141.6-See table below





NTNV-11AC40SISO-Ant1-5190-5141.6~5150-See table below













NTNV-11AC40SISO-Ant1-5230-5250~5251-See table below




NTNV-11AC40SISO-Ant1-5230-5251~5270-See table below






NTNV-11AC40SISO-Ant1-5230-5270~5278.4-See table below




NTNV-11AC40SISO-Ant1-5230-5278.4~26000-See table below






NTNV-11AC40SISO-Ant1-5270-30~5221.6-See table below




NTNV-11AC40SISO-Ant1-5270-5221.6~5230-See table below






NTVN-11AC40SISO-Ant1-5270-5230~5249-See table below




NTVN-11AC40SISO-Ant1-5270-5249~5250-See table below







NTNV-11AC40SISO-Ant1-5270-5350~5348.4-PASS




NTNV-11AC40SISO-Ant1-5270-5348.4~26000-PASS











NTNV-11AC40SISO-Ant1-5310-5350~5348.4-See table below




NTNV-11AC40SISO-Ant1-5310-5348.4~26000-See table below







NTNV-11AC40SISO-Ant1-5510-30~5460-PASS





NTNV-11AC40SISO-Ant1-5510-5460~5470-See table below
















NTNV-11AX20SISO-Ant1-5180-5142~5150-See table below




NTNV-11AX20SISO-Ant1-5180-5250~5250.2-PASS







NTNV-11AX20SISO-Ant1-5180-5250.2~5251-PASS





NTNV-11AX20SISO-Ant1-5180-5251~5260-PASS



















NTNV-11AX20SISO-Ant1-5240-5142~5150-PASS




NTNV-11AX20SISO-Ant1-5240-5250~5250.2-See table below






NTNV-11AX20SISO-Ant1-5240-5250.2~5251-See table below




NTNV-11AX20SISO-Ant1-5240-5251~5260-See table below






NTNV-11AX20SISO-Ant1-5240-5260~5266.7-See table below




NTNV-11AX20SISO-Ant1-5240-5266.7~26000-PASS






NTNV-11AX20SISO-Ant1-5260-30~5233.3-See table below




NTNV-11AX20SISO-Ant1-5260-5233.3~5240-See table below






NTNV-11AX20SISO-Ant1-5260-5240~5249-See table below




NTNV-11AX20SISO-Ant1-5260-5249~5249.8-See table below







NTNV-11AX20SISO-Ant1-5260-5249.8~5250-See table below





NTNV-11AX20SISO-Ant1-5260-5350~26000-PASS

















NTNV-11AX20SISO-Ant1-5320-5240~5249-PASS




NTNV-11AX20SISO-Ant1-5320-5249~5249.8-PASS









NTNV-11AX20SISO-Ant1-5500-30~5460-PASS





NTNV-11AX20SISO-Ant1-5500-5460~5470-See table below
















NTNV-11AX20SISO-Ant1-5700-5745~5765-PASS




NTNV-11AX20SISO-Ant1-5700-5765~26000-See table below






NTNV-11AX40SISO-Ant1-5190-30~5141.6-See table below




NTNV-11AX40SISO-Ant1-5190-5141.6~5150-See table below







NTNV-11AX40SISO-Ant1-5190-5250~5251-PASS




NTNV-11AX40SISO-Ant1-5190-5251~5270-PASS











NTNV-11AX40SISO-Ant1-5230-5250~5251-See table below




NTNV-11AX40SISO-Ant1-5230-5251~5270-See table below






NTNV-11AX40SISO-Ant1-5230-5270~5278.4-See table below




NTNV-11AX40SISO-Ant1-5230-5278.4~26000-See table below






NTNV-11AX40SISO-Ant1-5270-30~5221.6-See table below




NTNV-11AX40SISO-Ant1-5270-5221.6~5230-See table below






NTNV-11AX40SISO-Ant1-5270-5230~5249-See table below




NTNV-11AX40SISO-Ant1-5270-5249~5250-See table below







NTNV-11AX40SISO-Ant1-5270-5350~5348.4-PASS




NTNV-11AX40SISO-Ant1-5270-5348.4~26000-PASS











NTNV-11AX40SISO-Ant1-5310-5350~5348.4-See table below




NTNV-11AX40SISO-Ant1-5310-5348.4~26000-See table below







NTVN-11AX40SISO-Ant1-5510-30~5460-PASS





NTVN-11AX40SISO-Ant1-5510-5460~5470-See table below














Test Graphs_Step2



NTNV-11A-Ant1-5240-5250~5251-PASS





NTNV-11A-Ant1-5240-5251~5260-PASS

