




Appendix A: Frequency Error

Test Graphs






NTNV_GFSK_1M_Ant1_2440.3




NTNV_GFSK_1M_Ant1_2470.3


Appendix B: Antenna Power

Test Graphs






NTNV_GFSK_1M_Ant1_2440.3




NTNV_GFSK_1M_Ant1_2470.3


Appendix C: Occupied Bandwidth

Test Graphs






NTNV_GFSK_1M_Ant1_2440.3




NTNV_GFSK_1M_Ant1_2470.3


Appendix D: Spread Bandwidth

Test Graphs







NTNV_GFSK_1M_Ant1_2440.3




NTNV_GFSK_1M_Ant1_2470.3

Test Graphs







NTNV_GFSK_1M_Ant1_2410.3_1000~2387




NTNV_GFSK_1M_Ant1_2410.3_2387~2400




NTNV_GFSK_1M_Ant1_2410.3_2483.5~2496.5




NTNV_GFSK_1M_Ant1_2410.3_2496.5~13000




NTNV_GFSK_1M_Ant1_2440.3_30~1000




NTNV_GFSK_1M_Ant1_2440.3_1000~2387




NTNV_GFSK_1M_Ant1_2440.3_2387~2400




NTNV_GFSK_1M_Ant1_2440.3_2483.5~2496.5




NTNV_GFSK_1M_Ant1_2440.3_2496.5~13000




NTNV_GFSK_1M_Ant1_2470.3_30~1000




NTNV_GFSK_1M_Ant1_2470.3_1000~2387



NTNV_GFSK_1M_Ant1_2470.3_2387~2400



NTNV_GFSK_1M_Ant1_2470.3_2483.5~2496.5



NTNV_GFSK_1M_Ant1_2470.3_2496.5~13000