




NTVN-11N20MIMO-Ant1-5260-5240~5249-PASS




NTVN-11N20MIMO-Ant1-5260-5240~5249-PASS




NTVN-11N20MIMO-Ant2-5260-5240~5249-PASS



NTVN-11N20MIMO-Ant2-5260-5240~5249-PASS





NTVN-11N20MIMO-Ant3-5260-5240~5249-PASS





NTVN-11N20MIMO-Ant3-5260-5240~5249-PASS









































 01:21:24 PM 03/16/2026	 01:21:59 PM 03/16/2026
NTNV-11N20MIMO-Ant1-5320-5233.3~5240-PA SS	NTNV-11N20MIMO-Ant1-5320-5233.3~5240-PA SS
 01:23:08 PM 03/16/2026	 01:23:41 PM 03/16/2026
NTNV-11N20MIMO-Ant2-5320-5233.3~5240-PA SS	NTNV-11N20MIMO-Ant2-5320-5233.3~5240-PA SS



NTNV-11N20MIMO-Ant3-5320-5233.3~5240-PA
SSNTNV-11N20MIMO-Ant3-5320-5233.3~5240-PA
SS



NTNV-11N40SISO-Ant1-5270-30~5221.6-PASS




NTNV-11N40SISO-Ant1-5270-30~5221.6-PASS




NTNV-11N40SISO-Ant1-5270-30~5221.6-PASS  04:13:42 AM 02/05/2026	NTNV-11N40SISO-Ant1-5270-30~5221.6-PASS  04:13:52 AM 02/05/2026
NTNV-11N40SISO-Ant2-5270-30~5221.6-PASS  02:14:25 AM 02/05/2026	NTNV-11N40SISO-Ant2-5270-30~5221.6-PASS  02:16:35 AM 02/05/2026
NTNV-11N40SISO-Ant1-5270-5221.6~5230-PAS S	NTNV-11N40SISO-Ant1-5270-5221.6~5230-PAS S

 04:14:14 AM 02/05/2026	 04:14:24 AM 02/05/2026
NTNV-11N40SISO-Ant2-5270-5221.6~5230-PAS S	NTNV-11N40SISO-Ant2-5270-5221.6~5230-PAS S
 11:29:25 AM 03/16/2026	 11:29:35 AM 03/16/2026
NTNV-11N40SISO-Ant3-5270-5221.6~5230-PAS S	NTNV-11N40SISO-Ant3-5270-5221.6~5230-PAS S




NTNV-11N40SISO-Ant1-5270-5230~5249-PASS




NTNV-11N40SISO-Ant1-5270-5230~5249-PASS



NTNV-11N40SISO-Ant1-5270-5249~5250-PASS







NTNV-11N40SISO-Ant1-5270-5249~5250-PASS





NTNV-11N40SISO-Ant2-5310-5221.6~5230-PAS





NTNV-11N40SISO-Ant2-5310-5221.6~5230-PAS


S	
	
NTNV-11N40SISO-Ant3-5310-5221.6~5230-PAS	
S	
	
NTNV-11N40SISO-Ant1-5310-5350~5358.4-PAS	
S	











































 02:26:58 AM 02/15/2026	 02:27:09 AM 02/15/2026
NTNV-11AC20SISO-Ant1-5260-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant1-5260-5233.3~5240-PA SS
 03:08:19 PM 02/14/2026	 03:08:30 PM 02/14/2026
NTNV-11AC20SISO-Ant2-5260-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant2-5260-5233.3~5240-PA SS



 11:37:54 AM 02/15/2026	 11:38:09 AM 02/15/2026
NTNV-11AC20SISO-Ant3-5260-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant3-5260-5233.3~5240-PA SS
 02:27:31 AM 02/05/2026	 02:27:41 AM 02/05/2026
NTNV-11AC20SISO-Ant1-5260-5240~5249-PAS S	NTNV-11AC20SISO-Ant1-5260-5240~5249-PAS S



 09:09:51 PM 03/14/2026	 09:09:01 PM 09/14/2026
NTVN-11AC20SISO-Ant2-5260-5240~5249-PAS S	NTNV-11AC20SISO-Ant2-5260-5240~5249-PAS S
 11:38:25 AM 03/14/2026	 11:38:35 AM 03/14/2026
NTVN-11AC20SISO-Ant3-5260-5240~5249-PAS S	NTNV-11AC20SISO-Ant3-5260-5240~5249-PAS S




 02:28:03 AM 02/05/2026	 02:28:13 AM 02/05/2026
NTVN-11AC20SISO-Ant1-5260-5249~5250-PAS S	NTNV-11AC20SISO-Ant1-5260-5249~5250-PAS S
 03:09:23 PM 03/14/2026	 03:09:33 PM 03/14/2026
NTNV-11AC20SISO-Ant2-5260-5249~5250-PAS S	NTNV-11AC20SISO-Ant2-5260-5249~5250-PAS S

 11:39:56 AM 02/16/2026	 11:39:06 AM 02/16/2026
NTVN-11AC20SISO-Ant3-5260-5249~5250-PAS S	NTVN-11AC20SISO-Ant3-5260-5249~5250-PAS S
 02:30:55 AM 02/05/2026	 02:31:06 AM 02/05/2026
NTVN-11AC20SISO-Ant1-5280-5233.3~5240-PA SS	NTVN-11AC20SISO-Ant1-5280-5233.3~5240-PA SS

 04:44:17 PM 03/14/2026	 04:44:26 PM 03/14/2026
NTNV-11AC20SISO-Ant2-5280-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant2-5280-5233.3~5240-PA SS
 11:40:05 AM 03/14/2026	 11:40:15 AM 03/14/2026
NTNV-11AC20SISO-Ant3-5280-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant3-5280-5233.3~5240-PA SS

 02:54:50 AM 02/15/2026	 02:55:00 AM 02/15/2026
NTNV-11AC20SISO-Ant1-5300-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant1-5300-5233.3~5240-PA SS
 04:47:13 PM 02/14/2026	 04:47:23 PM 02/14/2026
NTNV-11AC20SISO-Ant2-5300-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant2-5300-5233.3~5240-PA SS

 11:42:59 AM 02/15/2026	 11:42:09 AM 02/15/2026
NTNV-11AC20SISO-Ant3-5300-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant3-5300-5233.3~5240-PA SS
 02:38:15 AM 02/05/2026	 02:38:15 AM 02/05/2026
NTNV-11AC20SISO-Ant1-5320-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant1-5320-5233.3~5240-PA SS

 04:51:22 PM 03/14/2026	 04:51:32 PM 03/14/2026
NTNV-11AC20SISO-Ant2-5320-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant2-5320-5233.3~5240-PA SS
 11:44:27 AM 03/14/2026	 11:44:37 AM 03/14/2026
NTNV-11AC20SISO-Ant3-5320-5233.3~5240-PA SS	NTNV-11AC20SISO-Ant3-5320-5233.3~5240-PA SS