



External Photos
Outview: A5W Pic 1



Outview: A5W Pic 2






Outview: A5W Pic 3




Outview: A5W Pic 4






Outview: A5W Pic 5



Outview: A5W Pic 6





Outview: A5W Pic 7




Outview: A5W Pic 8




Provided by the customer.

Accessory: K2V4 Pic 1




Accessory: K2V4 Pic 2




Provided by the customer.

Accessory: K2X-N Pic 1



Accessory: K2X-N Pic 2





Accessory: Power Source (不隨貨販售) Pic 1




Accessory: Power Source (不隨貨販售) Pic 2





Accessory: Power Source (不隨貨販售) Pic 3



Accessory: Power Source (不隨貨販售) Pic 4






報告編號 : 4790126274-EP


頁碼 : 9 of 19

報告發行日期 : 2022/1/25

Accessory: Power Source (不隨貨販售) Pic 5



Accessory: Power Source (不隨貨販售) Pic 6



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948