



Appendix A: Frequency Error


Test Graphs







Appendix B: Antenna Power

Test Graphs







NTNV_BLE_1M_Ant1_2480




NTNV_BLE_2M_Ant1_2402







Appendix C: Occupied Bandwidth

Test Graphs







NTNV_BLE_1M_Ant1_2480




NTNV_BLE_2M_Ant1_2402







Appendix D: Spread Bandwidth

Test Graphs







NTNV_BLE_1M_Ant1_2480



NTNV_BLE_2M_Ant1_2402







Appendix E: Spurious Emission of TX

Test Graphs









NTNV_BLE_1M_Ant1_2402_2387~2400



NTNV_BLE_1M_Ant1_2402_2483.5~2496.5









NTNV_BLE_1M_Ant1_2440_2387~2400




NTNV_BLE_1M_Ant1_2440_2483.5~2496.5











NTNV_BLE_1M_Ant1_2480_2387~2400



NTNV_BLE_1M_Ant1_2480_2483.5~2496.5










NTNV_BLE_2M_Ant1_2402_2387~2400




NTNV_BLE_2M_Ant1_2402_2483.5~2496.5










NTNV_BLE_2M_Ant1_2440_2387~2400




NTNV_BLE_2M_Ant1_2440_2483.5~2496.5








NTNV_BLE_2M_Ant1_2480_2387~2400




NTNV_BLE_2M_Ant1_2480_2483.5~2496.5




NTNV_BLE_2M_Ant1_2480_2496.5~13000


Appendix F: Spurious Emission of RX

Test Graphs









NTNV_BLE_1M_Ant1_2440_30~1000




NTNV_BLE_1M_Ant1_2440_1000~12500







NTNV_BLE_2M_Ant1_2402_1000~12500



NTNV_BLE_2M_Ant1_2440_30~1000

