


## Appendix A: Frequency Error

### Test Graphs








NTNV\_BLE\_1M\_Ant1\_2480

## Appendix B: Antenna Power

### Test Graphs










## Appendix C: Occupied Bandwidth

### Test Graphs









## Appendix D: Spread Bandwidth

### Test Graphs







NTNV\_BLE\_1M\_Ant1\_2480



NTNV\_BLE\_2M\_Ant1\_2402







## Appendix E: Spurious Emission of TX

### Test Graphs






NTNV\_BLE\_1M\_Ant1\_2402\_2387~2400



NTNV\_BLE\_1M\_Ant1\_2402\_2483.5~2496.5








NTNV\_BLE\_1M\_Ant1\_2440\_2387~2400



NTNV\_BLE\_1M\_Ant1\_2440\_2483.5~2496.5









NTNV\_BLE\_1M\_Ant1\_2480\_2387~2400




NTNV\_BLE\_1M\_Ant1\_2480\_2483.5~2496.5









NTNV\_BLE\_2M\_Ant1\_2402\_2387~2400




NTNV\_BLE\_2M\_Ant1\_2402\_2483.5~2496.5









NTNV\_BLE\_2M\_Ant1\_2440\_2387~2400




NTNV\_BLE\_2M\_Ant1\_2440\_2483.5~2496.5








NTNV\_BLE\_2M\_Ant1\_2480\_2387~2400




NTNV\_BLE\_2M\_Ant1\_2480\_2483.5~2496.5







## Appendix F: Spurious Emission of RX

### Test Graphs







NTNV\_BLE\_1M\_Ant1\_2440\_30~1000




NTNV\_BLE\_1M\_Ant1\_2440\_1000~12500







NTNV\_BLE\_2M\_Ant1\_2402\_1000~12500



NTNV\_BLE\_2M\_Ant1\_2440\_30~1000

