



Appendix A: Frequency Error


Test Graphs






Appendix B: Antenna Power

Test Graphs






Appendix C: Occupied Bandwidth

Test Graphs






Appendix D: Spread Bandwidth


Test Graphs






Appendix E: Spurious Emission of TX

Test Graphs








NTNV_GFSK_1M_Ant1_2402_2387~2400



NTNV_GFSK_1M_Ant1_2402_2483.5~2496.5










NTNV_GFSK_1M_Ant1_2440_2387~2400



NTNV_GFSK_1M_Ant1_2440_2483.5~2496.5








NTNV_GFSK_1M_Ant1_2480_2387~2400



NTNV_GFSK_1M_Ant1_2480_2483.5~2496.5



NTNV_GFSK_1M_Ant1_2480_2496.5~13000