























NTHV 11A Ant1 5320 5233.3~5240



NTHV 11A Ant1 5320 5240~5249



NTHV 11A Ant1 5320 5249~5250









































































Test Graphs_Step2





Appendix A

CN26ANFR 002


Page 185 of 387




Prüfbericht - Produkte
Test Report - Products








NTNV 11AC40SISO Ant1 5230 5250.17 Ant1





NTNV 11AC40SISO Ant1 5270 5248.53 Ant1


















Appendix A

CN26ANFR 002

Page 195 of 387



TÜVRheinland®

Prüfbericht - Produkte
Test Report - Products




Appendix A

CN26ANFR 002

Page 197 of 387

Prüfbericht - Produkte
Test Report - Products





Appendix A

CN26ANFR 002

Page 200 of 387



TÜVRheinland®

Prüfbericht - Produkte
Test Report - Products

