



Appendix A: Frequency Error


Test Graphs





Appendix B: Antenna Power


Test Graphs






Appendix C: Occupied Bandwidth


Test Graphs






Appendix D: Spread Bandwidth


Test Graphs






Appendix E: Spurious Emission of TX

Test Graphs






NTNV_BLE_1M_Ant1_2404_2387~2400



NTNV_BLE_1M_Ant1_2404_2483.5~2496.5




NTNV_BLE_1M_Ant1_2404_2496.5~13000




NTNV_BLE_1M_Ant1_2444_30~1000




NTNV_BLE_1M_Ant1_2444_1000~2387




NTNV_BLE_1M_Ant1_2444_2387~2400



NTNV_BLE_1M_Ant1_2444_2483.5~2496.5




NTNV_BLE_1M_Ant1_2444_2496.5~13000




NTNV_BLE_1M_Ant1_2479_30~1000



NTNV_BLE_1M_Ant1_2479_1000~2387



NTNV_BLE_1M_Ant1_2479_2387~2400



NTNV_BLE_1M_Ant1_2479_2483.5~2496.5

