










 12:54:52 AM 02/04/2026	 12:53:51 AM 02/03/2026
NTNV-11AX20SISO-Ant3-5220-5250.2~5251-PA SS	NTNV-11AX20SISO-Ant1-5220-5251~5260-PAS S
 03:23:42 AM 02/03/2026	 12:35:03 AM 02/04/2026
NTNV-11AX20SISO-Ant2-5220-5251~5260-PAS S	NTNV-11AX20SISO-Ant3-5220-5251~5260-PAS S

 12:24:01 AM 02/03/2026	 03:23:53 AM 02/03/2026
NTNV-11AX20SISO-Ant1-5220-5260~5266.7-PA SS	NTNV-11AX20SISO-Ant2-5220-5260~5266.7-PA SS
 12:35:13 AM 02/04/2026	 12:24:13 AM 02/03/2026
NTNV-11AX20SISO-Ant3-5220-5260~5266.7-PA SS	NTNV-11AX20SISO-Ant1-5220-5266.7~26000-S ee table below




NTNV-11AX20SISO-Ant2-5220-5266.7~26000-P
ASS



NTNV-11AX20SISO-Ant3-5220-5266.7~26000-P
ASS










NTNV-11AX20SISO-Ant1-5240-30~5142-PASS











NTNV-11AX20SISO-Ant2-5240-30~5142-PASS




NTNV-11AX20SISO-Ant3-5240-30~5142-PASS	NTNV-11AX20SISO-Ant1-5240-5142~5150-PASS S
 04:41:52 AM 02/03/2026	 12:42:33 AM 02/04/2026
NTNV-11AX20SISO-Ant2-5240-5142~5150-PASS S	NTNV-11AX20SISO-Ant3-5240-5142~5150-PASS S
 12:36:39 AM 02/03/2026	 04:42:02 AM 02/03/2026
NTNV-11AX20SISO-Ant1-5240-5250~5250.2-See table below	NTNV-11AX20SISO-Ant2-5240-5250~5250.2-See table below

 12:42:44 AM 02/04/2026	 12:37:20 AM 02/03/2026
NTVN-11AX20SISO-Ant3-5240-5250~5250.2-Se e table below	NTVN-11AX20SISO-Ant1-5240-5250.2~5251-PA SS
 04:42:43 AM 02/03/2026	 12:43:25 AM 02/04/2026
NTVN-11AX20SISO-Ant2-5240-5250.2~5251-Se e table below	NTVN-11AX20SISO-Ant3-5240-5250.2~5251-PA SS


 12:37:30 AM 02/03/2026	 04:43:16 AM 02/03/2026
NTVN-11AX20SISO-Ant1-5240-5251~5260-PAS S	NTNV-11AX20SISO-Ant2-5240-5251~5260-PAS S
 12:43:35 AM 02/04/2026	 12:37:40 AM 02/03/2026
NTVN-11AX20SISO-Ant3-5240-5251~5260-PAS S	NTNV-11AX20SISO-Ant1-5240-5260~5266.7-PA SS

 04:43:27 AM 02/03/2026	 12:43:46 AM 02/04/2026
NTVN-11AX20SISO-Ant2-5240-5260~5266.7-PA SS	NTVN-11AX20SISO-Ant3-5240-5260~5266.7-PA SS
 12:37:52 AM 02/03/2026	 04:43:39 AM 02/03/2026
NTVN-11AX20SISO-Ant1-5240-5266.7~26000-P ASS	NTVN-11AX20SISO-Ant2-5240-5266.7~26000-P ASS




12:43:58 AM 02/04/2026

NTVN-11AX20SISO-Ant3-5240-5266.7~26000-P
ASS




11:45:19 PM 02/04/2026

NTVN-11AX20MIMO-Ant1-5180-30~5142-PASS



11:46:52 PM 02/04/2026

NTVN-11AX20MIMO-Ant2-5180-30~5142-PASS



11:48:26 PM 02/04/2026





NTVN-11AX20MIMO-Ant3-5180-30~5142-PASS






11:45:29 PM 02/04/2026







11:47:03 PM 02/04/2026

NTNV-11AX20MIMO-Ant1-5180-5142~5150-PAS S  11:48:37 PM 02/04/2026	NTNV-11AX20MIMO-Ant2-5180-5142~5150-PAS S  11:48:40 PM 02/04/2026
NTNV-11AX20MIMO-Ant3-5180-5142~5150-PAS S  11:47:14 PM 02/04/2026	NTNV-11AX20MIMO-Ant1-5180-5250~5250.2-P ASS  11:48:48 PM 02/04/2026
NTNV-11AX20MIMO-Ant2-5180-5250~5250.2-P ASS	NTNV-11AX20MIMO-Ant3-5180-5250~5250.2-P ASS



 11:45:51 PM 02/04/2026	 11:47:24 PM 02/04/2026
NTNV-11AX20MIMO-Ant1-5180-5250.2~5251-P ASS	NTNV-11AX20MIMO-Ant2-5180-5250.2~5251-P ASS
 11:48:58 PM 02/04/2026	 11:49:01 PM 02/04/2026
NTNV-11AX20MIMO-Ant3-5180-5250.2~5251-P ASS	NTNV-11AX20MIMO-Ant1-5180-5251~5260-PAS S




NTNV-11AX20MIMO-Ant2-5180-5251~5260-PAS S	NTNV-11AX20MIMO-Ant3-5180-5251~5260-PAS S
NTNV-11AX20MIMO-Ant1-5180-5260~5266.7-P ASS	NTNV-11AX20MIMO-Ant2-5180-5260~5266.7-P ASS





 11:49:19 PM 02/04/2026	 11:46:24 PM 02/04/2026
NTVN-11AX20MIMO-Ant3-5180-5260~5266.7-P ASS	NTVN-11AX20MIMO-Ant1-5180-5266.7~26000-P ASS
 11:47:58 PM 02/04/2026	 11:49:31 PM 02/04/2026
NTVN-11AX20MIMO-Ant2-5180-5266.7~26000-P ASS	NTVN-11AX20MIMO-Ant3-5180-5266.7~26000-P ASS







NTNV-11AX20MIMO-Ant2-5200-5142~5150-PAS S	NTNV-11AX20MIMO-Ant3-5200-5142~5150-PAS S
NTNV-11AX20MIMO-Ant1-5200-5250~5250.2-P ASS	NTNV-11AX20MIMO-Ant2-5200-5250~5250.2-P ASS
NTNV-11AX20MIMO-Ant3-5200-5250~5250.2-P ASS	NTNV-11AX20MIMO-Ant1-5200-5250.2~5251-P ASS



 11:57:42 PM 02/04/2026	 11:59:16 PM 02/04/2026
NTVN-11AX20MIMO-Ant2-5200-5250.2~5251-P ASS	NTVN-11AX20MIMO-Ant3-5200-5250.2~5251-P ASS
 11:58:19 PM 02/04/2026	 11:57:53 PM 02/04/2026
NTVN-11AX20MIMO-Ant1-5200-5251~5260-PAS S	NTVN-11AX20MIMO-Ant2-5200-5251~5260-PAS S

 11:59:27 PM 02/04/2026	 11:58:30 PM 02/04/2026
NTNV-11AX20MIMO-Ant3-5200-5251~5260-PAS S	NTNV-11AX20MIMO-Ant1-5200-5260~5266.7-P ASS
 11:59:03 PM 02/04/2026	 11:59:37 PM 02/04/2026
NTNV-11AX20MIMO-Ant2-5200-5260~5266.7-P ASS	NTNV-11AX20MIMO-Ant3-5200-5260~5266.7-P ASS

 11:58:42 PM 02/04/2026	 11:58:16 PM 02/04/2026
NTVN-11AX20MIMO-Ant1-5200-5266.7~26000-P ASS	NTVN-11AX20MIMO-Ant2-5200-5266.7~26000-P ASS
 11:59:49 PM 02/04/2026	 12:06:13 AM 02/05/2026
NTVN-11AX20MIMO-Ant3-5200-5266.7~26000-P ASS	NTVN-11AX20MIMO-Ant1-5220-30~5142-PASS




NTNV-11AX20MIMO-Ant3-5220-5142~5150-PAS S  12-08-30 AM 02/05/2026	NTNV-11AX20MIMO-Ant1-5220-5250~5250.2-P ASS  12-10-04 AM 02/05/2026
NTNV-11AX20MIMO-Ant2-5220-5250~5250.2-P ASS  12-06-45 AM 02/05/2026	NTNV-11AX20MIMO-Ant3-5220-5250~5250.2-P ASS  12-08-41 AM 02/05/2026
NTNV-11AX20MIMO-Ant1-5220-5250.2~5251-P ASS	NTNV-11AX20MIMO-Ant2-5220-5250.2~5251-P ASS

 12:10:15 AM 02/05/2026	 12:06:59 AM 02/05/2026
NTVN-11AX20MIMO-Ant3-5220-5250.2~5251-P ASS	NTVN-11AX20MIMO-Ant1-5220-5251~5260-PAS S
 12:09:52 AM 02/05/2026	 12:10:15 AM 02/05/2026
NTVN-11AX20MIMO-Ant2-5220-5251~5260-PAS S	NTVN-11AX20MIMO-Ant3-5220-5251~5260-PAS S

NTVN-11AX20MIMO-Ant1-5220-5260~5266.7-P ASS	NTNV-11AX20MIMO-Ant2-5220-5260~5266.7-P ASS
NTNV-11AX20MIMO-Ant3-5220-5260~5266.7-P ASS	NTNV-11AX20MIMO-Ant1-5220-5266.7~26000-P ASS




NTNV-11AX20MIMO-Ant2-5220-5266.7~26000-P
ASS




NTNV-11AX20MIMO-Ant3-5220-5266.7~26000-P
ASS










NTNV-11AX20MIMO-Ant1-5240-30~5142-PASS



NTNV-11AX20MIMO-Ant2-5240-30~5142-PASS










NTNV-11AX20MIMO-Ant3-5240-30~5142-PASS	NTNV-11AX20MIMO-Ant1-5240-5142~5150-PASS S
 12:19:04 AM 02/05/2026	 12:21:37 AM 02/05/2026
NTNV-11AX20MIMO-Ant2-5240-5142~5150-PASS S	NTNV-11AX20MIMO-Ant3-5240-5142~5150-PASS S
 12:16:41 AM 02/05/2026	 12:19:14 AM 02/05/2026
NTNV-11AX20MIMO-Ant1-5240-5250~5250.2-S ee table below	NTNV-11AX20MIMO-Ant2-5240-5250~5250.2-S ee table below




 12:22:49 AM 02/05/2026	 12:17:51 AM 02/05/2026
NTVN-11AX20MIMO-Ant3-5240-5250~5250.2-S see table below	NTNV-11AX20MIMO-Ant1-5240-5250.2~5251-P ASS
 12:20:25 AM 02/05/2026	 12:22:58 AM 02/05/2026
NTNV-11AX20MIMO-Ant2-5240-5250.2~5251-P ASS	NTNV-11AX20MIMO-Ant3-5240-5250.2~5251-P ASS




NTNV-11AX20MIMO-Ant1-5240-5251~5260-PAS S	NTNV-11AX20MIMO-Ant2-5240-5251~5260-PAS S
NTNV-11AX20MIMO-Ant3-5240-5251~5260-PAS S	NTNV-11AX20MIMO-Ant1-5240-5260~5266.7-P ASS


NTVN-11AX20MIMO-Ant2-5240-5260~5266.7-P ASS	NTVN-11AX20MIMO-Ant3-5240-5260~5266.7-P ASS
NTVN-11AX20MIMO-Ant1-5240-5266.7~26000-P ASS	NTVN-11AX20MIMO-Ant2-5240-5266.7~26000-P ASS


 12:23:31 AM 02/05/2026	 12:44:39 AM 02/03/2026
NTVN-11AX20MIMO-Ant3-5240-5266.7~26000-P ASS	NTVN-11AX40SISO-Ant1-5190-30~5141.6-PASS
 05:42:12 AM 02/03/2026	 12:50:43 AM 02/04/2026
NTVN-11AX40SISO-Ant2-5190-30~5141.6-PASS	NTVN-11AX40SISO-Ant3-5190-30~5141.6-See table below





 NTVN-11AX40SISO-Ant1-5190-5141.6~5150-PA SS	 NTVN-11AX40SISO-Ant2-5190-5141.6~5150-Se e table below
 NTVN-11AX40SISO-Ant3-5190-5141.6~5150-Se e table below	 NTVN-11AX40SISO-Ant1-5190-5250~5251-PAS S





 05:43:01 AM 02/03/2026	 12:51:30 AM 02/04/2026
NTVN-11AX40SISO-Ant2-5190-5250~5251-PAS S	NTVN-11AX40SISO-Ant3-5190-5250~5251-PAS S
 12:45:10 AM 02/03/2026	 05:43:12 AM 02/03/2026
NTVN-11AX40SISO-Ant1-5190-5251~5270-PAS S	NTVN-11AX40SISO-Ant2-5190-5251~5270-PAS S

 12:51:40 AM 02/04/2026	 12:45:21 AM 02/03/2026
NTVN-11AX40SISO-Ant3-5190-5251~5270-PAS S	NTNV-11AX40SISO-Ant1-5190-5270~5278.4-PA SS
 05:43:22 AM 02/03/2026	 12:51:51 AM 02/04/2026
NTVN-11AX40SISO-Ant2-5190-5270~5278.4-PA SS	NTNV-11AX40SISO-Ant3-5190-5270~5278.4-PA SS











NTNV-11AX40SISO-Ant3-5230-5141.6~5150-PA SS	NTNV-11AX40SISO-Ant1-5230-5250~5251-See table below
	
NTNV-11AX40SISO-Ant2-5230-5250~5251-See table below	NTNV-11AX40SISO-Ant3-5230-5250~5251-See table below
	
NTNV-11AX40SISO-Ant1-5230-5251~5270-PAS S	NTNV-11AX40SISO-Ant2-5230-5251~5270-See table below





 12:55:55 AM 02/04/2026	 12:55:41 AM 02/03/2026
NTVN-11AX40SISO-Ant3-5230-5251~5270-See table below	NTNV-11AX40SISO-Ant1-5230-5270~5278.4-PA SS
 05:48:04 AM 02/03/2026	 12:56:28 AM 02/04/2026
NTVN-11AX40SISO-Ant2-5230-5270~5278.4-See e table below	NTNV-11AX40SISO-Ant3-5230-5270~5278.4-PA SS





NTVN-11AX40SISO-Ant1-5230-5278.4~26000-P ASS	NTVN-11AX40SISO-Ant2-5230-5278.4~26000-P ASS
NTVN-11AX40SISO-Ant3-5230-5278.4~26000-P ASS	NTVN-11AX40MIMO-Ant1-5190-30~5141.6-PAS S




NTNV-11AX40MIMO-Ant2-5190-30~5141.6-PAS S	NTNV-11AX40MIMO-Ant3-5190-30~5141.6-PAS S
NTNV-11AX40MIMO-Ant1-5190-5141.6~5150-P ASS	NTNV-11AX40MIMO-Ant2-5190-5141.6~5150-P ASS





 12:35:44 AM 02/05/2026	 12:34:08 AM 02/05/2026
NTVN-11AX40MIMO-Ant3-5190-5141.6~5150-P ASS	NTVN-11AX40MIMO-Ant1-5190-5250~5251-PAS S
 12:35:31 AM 02/05/2026	 12:36:54 AM 02/05/2026
NTVN-11AX40MIMO-Ant2-5190-5250~5251-PAS S	NTVN-11AX40MIMO-Ant3-5190-5250~5251-PAS S

 12:34:19 AM 02/05/2026	 12:35:42 AM 02/05/2026
NTVN-11AX40MIMO-Ant1-5190-5251~5270-PAS S	NTVN-11AX40MIMO-Ant2-5190-5251~5270-PAS S
 12:37:05 AM 02/05/2026	 12:34:29 AM 02/05/2026
NTVN-11AX40MIMO-Ant3-5190-5251~5270-PAS S	NTVN-11AX40MIMO-Ant1-5190-5270~5278.4-P ASS

 12:35:52 AM 02/05/2026	 12:37:16 AM 02/05/2026
NTVN-11AX40MIMO-Ant2-5190-5270~5278.4-P ASS	NTVN-11AX40MIMO-Ant3-5190-5270~5278.4-P ASS
 12:36:41 AM 02/05/2026	 12:36:05 AM 02/05/2026
NTVN-11AX40MIMO-Ant1-5190-5278.4~26000-P ASS	NTVN-11AX40MIMO-Ant2-5190-5278.4~26000-P ASS

 12:37:29 AM 02/05/2026	 12:43:09 AM 02/05/2026
NTVN-11AX40MIMO-Ant3-5190-5278.4~26000-P ASS	NTVN-11AX40MIMO-Ant1-5230-30~5141.6-PAS S
 12:44:26 AM 02/05/2026	 12:45:49 AM 02/05/2026
NTVN-11AX40MIMO-Ant2-5230-30~5141.6-PAS S	NTVN-11AX40MIMO-Ant3-5230-30~5141.6-PAS S

 NTNV-11AX40MIMO-Ant1-5230-5141.6~5150-P ASS	 NTNV-11AX40MIMO-Ant2-5230-5141.6~5150-P ASS
 NTNV-11AX40MIMO-Ant3-5230-5141.6~5150-P ASS	 NTNV-11AX40MIMO-Ant1-5230-5250~5251-PAS S

 12:44:47 AM 02/05/2026	 12:46:10 AM 02/05/2026
NTVN-11AX40MIMO-Ant2-5230-5250~5251-PAS S	NTVN-11AX40MIMO-Ant3-5230-5250~5251-PAS S
 12:43:55 AM 02/05/2026	 12:44:58 AM 02/05/2026
NTVN-11AX40MIMO-Ant1-5230-5251~5270-PAS S	NTVN-11AX40MIMO-Ant2-5230-5251~5270-PAS S

NTVN-11AX40MIMO-Ant3-5230-5251~5270-PAS S	NTNV-11AX40MIMO-Ant1-5230-5270~5278.4-P ASS
NTNV-11AX40MIMO-Ant2-5230-5270~5278.4-P ASS	NTNV-11AX40MIMO-Ant3-5230-5270~5278.4-P ASS

NTVN-11AX40MIMO-Ant1-5230-5278.4~26000-P ASS	NTVN-11AX40MIMO-Ant2-5230-5278.4~26000-P ASS
NTVN-11AX40MIMO-Ant3-5230-5278.4~26000-P ASS	NTVN-11AX80SISO-Ant1-5210-30~5123.2-See table below