




Appendix A: Frequency Error



Test Graphs






Appendix B: Antenna Power


Test Graphs





Appendix C: Occupied Bandwidth


Test Graphs





Appendix D: Spread Bandwidth


Test Graphs







Appendix E: Spurious Emission of TX

Test Graphs







NTNV_GFSK_Ant1_2405_2387~2400



NTNV_GFSK_Ant1_2405_2483.5~2496.5




NTNV_GFSK_Ant1_2405_2496.5~13000




NTNV_GFSK_Ant1_2440_30~1000




NTNV_GFSK_Ant1_2440_1000~2387



NTNV_GFSK_Ant1_2440_2387~2400



NTNV_GFSK_Ant1_2440_2483.5~2496.5




NTNV_GFSK_Ant1_2440_2496.5~13000




NTNV_GFSK_Ant1_2475_30~1000



NTNV_GFSK_Ant1_2475_1000~2387



NTNV_GFSK_Ant1_2475_2387~2400



NTNV_GFSK_Ant1_2475_2483.5~2496.5

