






















 04/02/08 PM 03/16/2026	 03/19/08 PM 03/16/2026
NTNV-11AC160MIMO-Ant3-5250-5350~5400.4- PASS	NTNV-11AC160MIMO-Ant1-5250-5400.4~26000 -PASS
 04/00/04 PM 03/16/2026	 04/01/20 PM 03/16/2026
NTNV-11AC160MIMO-Ant2-5250-5400.4~26000 -PASS	NTNV-11AC160MIMO-Ant3-5250-5400.4~26000 -PASS




 09:05:23 AM 02/05/2026	 04:29:46 PM 03/14/2026
NTNV-11AX20SISO-Ant1-5260-30~5233.3-PASS	
 11:51:57 AM 03/16/2026	 03:05:34 AM 02/05/2026
NTNV-11AX20SISO-Ant3-5260-30~5233.3-PASS	
NTNV-11AX20SISO-Ant1-5260-5233.3~5240-See table below	
 04:29:56 PM 03/14/2026	 11:52:07 AM 03/14/2026



NTNV-11AX20SISO-Ant2-5260-5233.3~5240-See table below	NTNV-11AX20SISO-Ant3-5260-5233.3~5240-See table below
	
NTNV-11AX20SISO-Ant1-5260-5240~5249-PASS	NTNV-11AX20SISO-Ant2-5260-5240~5249-See table below
	
NTNV-11AX20SISO-Ant3-5260-5240~5249-See table below	NTNV-11AX20SISO-Ant1-5260-5249~5249.8-PASS




 04:52:00 PM 02/14/2026	 11:53:11 AM 02/15/2026
NTVN-11AX20SISO-Ant2-5260-5249~5249.8-Se e table below	NTNV-11AX20SISO-Ant3-5260-5249~5249.8-Se e table below
 03:04:27 AM 02/05/2026	 04:31:33 PM 02/14/2026
NTNV-11AX20SISO-Ant1-5260-5249.8~5250-PA SS	NTNV-11AX20SISO-Ant2-5260-5249.8~5250-Se e table below






 11:53:43 AM 03/14/2026	 03:06:39 AM 02/05/2025
NTNV-11AX20SISO-Ant3-5260-5249.8~5250-Se e table below	NTNV-11AX20SISO-Ant1-5260-5350~26000-PA SS
 04:32:07 PM 03/14/2026	 11:54:16 AM 03/14/2026
NTNV-11AX20SISO-Ant2-5260-5350~26000-PA SS	NTNV-11AX20SISO-Ant3-5260-5350~26000-PA SS









NTNV-11AX20SISO-Ant2-5280-5233.3~5240-Se e table below	NTNV-11AX20SISO-Ant3-5280-5233.3~5240-Se e table below
 03:10:05 AM 02/05/2026	 11:02:59 AM 03/16/2026
NTNV-11AX20SISO-Ant1-5280-5240~5249-PAS S	NTNV-11AX20SISO-Ant2-5280-5240~5249-PAS S
 11:56:41 AM 03/16/2026	 03:10:15 AM 02/05/2026
NTNV-11AX20SISO-Ant3-5280-5240~5249-PAS S	NTNV-11AX20SISO-Ant1-5280-5249~5249.8-PA SS




 11:03:09 AM 03/16/2026	 11:04:51 AM 03/16/2026
NTNV-11AX20SISO-Ant2-5280-5249~5249.8-PA SS	NTNV-11AX20SISO-Ant3-5280-5249~5249.8-PA SS
 03:10:24 AM 02/05/2026	 11:03:19 AM 03/16/2026
NTNV-11AX20SISO-Ant1-5280-5249.8~5250-PA SS	NTNV-11AX20SISO-Ant2-5280-5249.8~5250-PA SS





 11:57:01 AM 03/16/2026	 03:10:39 AM 02/05/2025
NTVN-11AX20SISO-Ant3-5280-5249.8~5250-PA SS	NTNV-11AX20SISO-Ant1-5280-5350~26000-PA SS
 11:03:31 AM 03/16/2026	 11:57:13 AM 03/16/2026
NTNV-11AX20SISO-Ant2-5280-5350~26000-PA SS	NTNV-11AX20SISO-Ant3-5280-5350~26000-PA SS



 09:12:45 AM 02/05/2026	 11:04:02 AM 02/05/2026
NTNV-11AX20SISO-Ant1-5300-30~5233.3-PASS	
 11:57:42 AM 02/05/2026	 03:12:56 AM 02/05/2026
NTNV-11AX20SISO-Ant3-5300-30~5233.3-PASS	
NTNV-11AX20SISO-Ant1-5300-5233.3~5240-See table below	
 11:04:13 AM 02/05/2026	 11:57:52 AM 02/05/2026



NTNV-11AX20SISO-Ant2-5300-5233.3~5240-Se e table below	NTNV-11AX20SISO-Ant3-5300-5233.3~5240-Se e table below
	
NTNV-11AX20SISO-Ant1-5300-5240~5249-PAS S	NTNV-11AX20SISO-Ant2-5300-5240~5249-PAS S
	
NTNV-11AX20SISO-Ant3-5300-5240~5249-PAS S	NTNV-11AX20SISO-Ant1-5300-5249~5249.8-PA SS




 11:04:54 AM 02/15/2026	 11:58:33 AM 02/15/2026
NTNV-11AX20SISO-Ant2-5300-5249~5249.8-PA SS	NTNV-11AX20SISO-Ant3-5300-5249~5249.8-PA SS
 03:13:49 AM 02/05/2026	 11:05:04 AM 02/15/2026
NTNV-11AX20SISO-Ant1-5300-5249.8~5250-PA SS	NTNV-11AX20SISO-Ant2-5300-5249.8~5250-PA SS





 11:59:44 AM 03/16/2026	 03:14:01 AM 02/05/2025
NTNV-11AX20SISO-Ant3-5300-5249.8~5250-PA SS	NTNV-11AX20SISO-Ant1-5300-5350~26000-PA SS
 11:05:16 AM 03/16/2026	 11:58:55 AM 03/16/2026
NTNV-11AX20SISO-Ant2-5300-5350~26000-PA SS	NTNV-11AX20SISO-Ant3-5300-5350~26000-PA SS




 09:16:24 AM 02/05/2026	 11:05:49 AM 02/05/2026
NTNV-11AX20SISO-Ant1-5320-30~5233.3-PASS	
 12:00:06 PM 02/16/2026	 03:16:35 AM 02/05/2026
NTNV-11AX20SISO-Ant3-5320-30~5233.3-PASS	
NTNV-11AX20SISO-Ant1-5320-5233.3~5240-Se e table below	
 11:05:57 AM 02/16/2026	 12:00:16 PM 02/16/2026





NTNV-11AX20SISO-Ant2-5320-5233.3~5240-Se e table below	NTNV-11AX20SISO-Ant3-5320-5233.3~5240-Se e table below
 03:17:07 AM 02/05/2026	 11:06:28 AM 03/14/2026
NTNV-11AX20SISO-Ant1-5320-5240~5249-PAS S	NTNV-11AX20SISO-Ant2-5320-5240~5249-PAS S
 12:00:47 PM 02/05/2026	 03:17:18 AM 02/05/2026
NTNV-11AX20SISO-Ant3-5320-5240~5249-PAS S	NTNV-11AX20SISO-Ant1-5320-5249~5249.8-PA SS





 11:06:38 AM 02/15/2026	 12:00:58 PM 02/15/2026
NTNV-11AX20SISO-Ant2-5320-5249~5249.8-PA SS	NTNV-11AX20SISO-Ant3-5320-5249~5249.8-PA SS
 03:17:28 AM 02/15/2026	 11:06:48 AM 02/15/2026
NTNV-11AX20SISO-Ant1-5320-5249.8~5250-PA SS	NTNV-11AX20SISO-Ant2-5320-5249.8~5250-PA SS

 12:02:08 PM 03/16/2026	 03:17:40 AM 03/16/2026
NTVN-11AX20SISO-Ant3-5320-5249.8~5250-PA SS	NTNV-11AX20SISO-Ant1-5320-5350~26000-PA SS
 11:07:00 AM 03/16/2026	 12:01:19 PM 03/16/2026
NTNV-11AX20SISO-Ant2-5320-5350~26000-PA SS	NTNV-11AX20SISO-Ant3-5320-5350~26000-PA SS




 02:22:47 PM 02/16/2026	 02:25:30 PM 02/16/2026
NTVN-11AX20MIMO-Ant1-5260-30~5233.3-PAS S	NTVN-11AX20MIMO-Ant2-5260-30~5233.3-PAS S
 02:30:55 PM 02/16/2026	 02:22:58 PM 02/16/2026
NTVN-11AX20MIMO-Ant3-5260-30~5233.3-PAS S	NTVN-11AX20MIMO-Ant1-5260-5233.3~5240-S see table below





 02:25:41 PM 03/16/2026	 02:30:45 PM 03/16/2026
NTVN-11AX20MIMO-Ant2-5260-5233.3~5240-S ee table below	NTNV-11AX20MIMO-Ant3-5260-5233.3~5240-S ee table below
 02:23:55 PM 03/16/2026	 02:26:38 PM 03/16/2026
NTNV-11AX20MIMO-Ant1-5260-5240~5249-See table below	NTNV-11AX20MIMO-Ant2-5260-5240~5249-See table below

 02:52:42 PM 03/16/2026	 02:24:06 PM 03/16/2026
NTNV-11AX20MIMO-Ant3-5260-5240~5249-See table below	NTNV-11AX20MIMO-Ant1-5260-5249~5249.8-S ee table below
 02:29:11 PM 03/16/2026	 02:32:39 PM 03/16/2026
NTNV-11AX20MIMO-Ant2-5260-5249~5249.8-S ee table below	NTNV-11AX20MIMO-Ant3-5260-5249~5249.8-S ee table below

 02:25:04 PM 03/16/2026	 02:30:09 PM 03/16/2026
NTNV-11AX20MIMO-Ant1-5260-5249.8~5250-S ee table below	NTNV-11AX20MIMO-Ant2-5260-5249.8~5250-S ee table below
 02:33:37 PM 03/16/2026	 02:25:16 PM 03/16/2026
NTNV-11AX20MIMO-Ant3-5260-5249.8~5250-S ee table below	NTNV-11AX20MIMO-Ant1-5260-5350~26000-PASS

NTNV-11AX20MIMO-Ant2-5260-5350~26000-PA SS	NTNV-11AX20MIMO-Ant3-5260-5350~26000-PA SS
NTNV-11AX20MIMO-Ant1-5280-30~5233.3-PAS S	NTNV-11AX20MIMO-Ant2-5280-30~5233.3-PAS S




	
NTNV-11AX20MIMO-Ant3-5280-30~5233.3-PAS	NTNV-11AX20MIMO-Ant1-5280-5233.3~5240-S ee table below
	
NTNV-11AX20MIMO-Ant2-5280-5233.3~5240-S ee table below	NTNV-11AX20MIMO-Ant3-5280-5233.3~5240-S ee table below




 02:37:52 PM 03/16/2026	 02:39:46 PM 03/16/2026
NTNV-11AX20MIMO-Ant1-5280-5240~5249-PAS S	NTNV-11AX20MIMO-Ant2-5280-5240~5249-PAS S
 02:42:40 PM 03/16/2026	 02:38:02 PM 03/16/2026
NTNV-11AX20MIMO-Ant3-5280-5240~5249-PAS S	NTNV-11AX20MIMO-Ant1-5280-5249~5249.8-P ASS




NTNV-11AX20MIMO-Ant2-5280-5249~5249.8-P ASS	NTNV-11AX20MIMO-Ant3-5280-5249~5249.8-P ASS
NTNV-11AX20MIMO-Ant1-5280-5249.8~5250-P ASS	NTNV-11AX20MIMO-Ant2-5280-5249.8~5250-P ASS




NTVN-11AX20MIMO-Ant3-5280-5249.8~5250-P ASS	NTVN-11AX20MIMO-Ant1-5280-5350~26000-PA SS
NTVN-11AX20MIMO-Ant2-5280-5350~26000-PA SS	NTVN-11AX20MIMO-Ant3-5280-5350~26000-PA SS




NTVN-11AX20MIMO-Ant1-5300-30~5233.3-PAS S	NTVN-11AX20MIMO-Ant2-5300-30~5233.3-PAS S
NTVN-11AX20MIMO-Ant3-5300-30~5233.3-PAS S	NTVN-11AX20MIMO-Ant1-5300-5233.3~5240-S see table below





 02:44:38 PM 03/16/2026	 02:46:33 PM 03/16/2026
NTVN-11AX20MIMO-Ant2-5300-5233.3~5240-S ee table below	NTVN-11AX20MIMO-Ant3-5300-5233.3~5240-S ee table below
 02:43:41 PM 03/16/2026	 02:45:36 PM 03/16/2026
NTVN-11AX20MIMO-Ant1-5300-5240~5249-PAS S	NTVN-11AX20MIMO-Ant2-5300-5240~5249-PAS S




 02:47:30 PM 03/16/2026	 02:48:51 PM 03/16/2026
NTVN-11AX20MIMO-Ant3-5300-5240~5249-PAS S	NTNV-11AX20MIMO-Ant1-5300-5249~5249.8-P ASS
 02:45:46 PM 03/16/2026	 02:47:40 PM 03/16/2026
NTNV-11AX20MIMO-Ant2-5300-5249~5249.8-P ASS	NTNV-11AX20MIMO-Ant3-5300-5249~5249.8-P ASS




 02:44:02 PM 03/16/2026	 02:45:56 PM 03/16/2026
NTVN-11AX20MIMO-Ant1-5300-5249.8~5250-P ASS	NTNV-11AX20MIMO-Ant2-5300-5249.8~5250-P ASS
 02:47:51 PM 03/16/2026	 02:44:13 PM 03/16/2026
NTNV-11AX20MIMO-Ant3-5300-5249.8~5250-P ASS	NTNV-11AX20MIMO-Ant1-5300-5350~26000-PA SS

 02:48:08 PM 03/16/2025	 02:48:02 PM 03/16/2025
NTNV-11AX20MIMO-Ant2-5300-5350~26000-PA SS	NTNV-11AX20MIMO-Ant3-5300-5350~26000-PA SS
 02:48:53 PM 03/16/2025	 02:50:47 PM 03/16/2025
NTNV-11AX20MIMO-Ant1-5320-30~5233.3-PAS S	NTNV-11AX20MIMO-Ant2-5320-30~5233.3-PAS S




 NTNV-11AX20MIMO-Ant3-5320-30~5233.3-PAS S	 NTNV-11AX20MIMO-Ant1-5320-5233.3~5240-S ee table below
 NTNV-11AX20MIMO-Ant2-5320-5233.3~5240-S ee table below	 NTNV-11AX20MIMO-Ant3-5320-5233.3~5240-S ee table below




 02:50:00 PM 03/16/2024	 02:51:55 PM 03/16/2024
NTVN-11AX20MIMO-Ant1-5320-5240~5249-PAS S	NTVN-11AX20MIMO-Ant2-5320-5240~5249-PAS S
 02:53:49 PM 03/16/2024	 02:55:11 PM 03/16/2024
NTVN-11AX20MIMO-Ant3-5320-5240~5249-PAS S	NTVN-11AX20MIMO-Ant1-5320-5249~5249.8-P ASS

 02:52:05 PM 03/16/2026	 02:54:00 PM 03/16/2026
NTVN-11AX20MIMO-Ant2-5320-5249~5249.8-P ASS	NTNV-11AX20MIMO-Ant3-5320-5249~5249.8-P ASS
 02:50:21 PM 03/16/2026	 02:52:15 PM 03/16/2026
NTNV-11AX20MIMO-Ant1-5320-5249.8~5250-P ASS	NTNV-11AX20MIMO-Ant2-5320-5249.8~5250-P ASS



 02:54:10 PM 03/16/2025	 02:50:39 PM 03/16/2025
NTVN-11AX20MIMO-Ant3-5320-5249.8~5250-P ASS	NTVN-11AX20MIMO-Ant1-5320-5350~26000-PA SS
 02:52:27 PM 03/16/2025	 02:54:22 PM 03/16/2025
NTVN-11AX20MIMO-Ant2-5320-5350~26000-PA SS	NTVN-11AX20MIMO-Ant3-5320-5350~26000-PA SS

NTVN-11AX40ISO-Ant1-5270-30~5221.6-See table below	NTNV-11AX40ISO-Ant2-5270-30~5221.6-PASS
NTVN-11AX40ISO-Ant3-5270-30~5221.6-PASS	NTVN-11AX40ISO-Ant1-5270-5221.6~5230-Se e table below


 11:07:44 AM 02/15/2026	 12:01:59 PM 02/15/2026
NTVN-11AX40SISO-Ant2-5270-5221.6~5230-Se e table below	NTNV-11AX40SISO-Ant3-5270-5221.6~5230-Se e table below
 03:23:27 AM 02/05/2026	 11:08:20 AM 02/15/2026
NTVN-11AX40SISO-Ant1-5270-5230~5249-PAS S	NTNV-11AX40SISO-Ant2-5270-5230~5249-PAS S

 12:02:26 PM 03/16/2026	 03:23:47 AM 03/16/2026
NTVN-11AX40SISO-Ant3-5270-5230~5249-PAS S	NTNV-11AX40SISO-Ant1-5270-5249~5250-PAS S
 11:09:30 AM 03/16/2026	 12:02:36 PM 03/16/2026
NTVN-11AX40SISO-Ant2-5270-5249~5250-PAS S	NTNV-11AX40SISO-Ant3-5270-5249~5250-PAS S

NTNV-11AX40SISO-Ant1-5270-5350~5358.4-PA SS	NTNV-11AX40SISO-Ant2-5270-5350~5358.4-PA SS
NTNV-11AX40SISO-Ant3-5270-5350~5358.4-PA SS	NTNV-11AX40SISO-Ant1-5270-5358.4~26000-P ASS





NTVN-11AX40SISO-Ant2-5270-5358.4~26000-P
ASSNTVN-11AX40SISO-Ant3-5270-5358.4~26000-P
ASS




NTVN-11AX40SISO-Ant1-5310-30~5221.6-PASS









NTVN-11AX40SISO-Ant2-5310-30~5221.6-PASS









NTNV-11AX40SISO-Ant3-5310-30~5221.6-PASS	NTNV-11AX40SISO-Ant1-5310-5221.6~5230-Se e table below
 11:10:35 AM 03/16/2026	 12:03:33 PM 03/16/2026
NTNV-11AX40SISO-Ant2-5310-5221.6~5230-Se e table below	NTNV-11AX40SISO-Ant3-5310-5221.6~5230-Se e table below
 03:26:58 AM 02/05/2026	 11:11:06 AM 03/16/2026
NTNV-11AX40SISO-Ant1-5310-5230~5249-PAS S	NTNV-11AX40SISO-Ant2-5310-5230~5249-PAS S

 12:04:04 PM 03/16/2026	 03:27:09 AM 03/16/2026
NTVN-11AX40SISO-Ant3-5310-5230~5249-PAS S	NTVN-11AX40SISO-Ant1-5310-5249~5250-PAS S
 11:11:14 AM 03/16/2026	 12:04:14 PM 03/16/2026
NTVN-11AX40SISO-Ant2-5310-5249~5250-PAS S	NTVN-11AX40SISO-Ant3-5310-5249~5250-PAS S

 03:27:19 AM 02/05/2026	 11:11:27 AM 02/05/2026
NTNV-11AX40SISO-Ant1-5310-5350~5358.4-PA SS	NTNV-11AX40SISO-Ant2-5310-5350~5358.4-PA SS
 12:04:24 PM 02/05/2026	 03:27:31 AM 02/05/2026
NTNV-11AX40SISO-Ant3-5310-5350~5358.4-PA SS	NTNV-11AX40SISO-Ant1-5310-5358.4~26000-P ASS

 11:11:38 AM 03/16/2026	 12:04:36 PM 03/16/2026
NTVN-11AX40SISO-Ant2-5310-5358.4~26000-P ASS	NTVN-11AX40SISO-Ant3-5310-5358.4~26000-P ASS
 02:56:53 PM 03/16/2026	 02:56:47 PM 03/16/2026
NTVN-11AX40MIMO-Ant1-5270-30~5221.6-PAS S	NTVN-11AX40MIMO-Ant2-5270-30~5221.6-PAS S

 02:58:41 PM 03/16/2026	 02:58:03 PM 03/16/2026
NTNV-11AX40MIMO-Ant3-5270-30~5221.6-PAS	NTNV-11AX40MIMO-Ant1-5270-5221.6~5230-S ee table below
 02:58:58 PM 03/16/2026	 02:58:52 PM 03/16/2026
NTNV-11AX40MIMO-Ant2-5270-5221.6~5230-S ee table below	NTNV-11AX40MIMO-Ant3-5270-5221.6~5230-S ee table below

 02:56:01 PM 03/16/2026	 02:57:55 PM 03/16/2026
NTVN-11AX40MIMO-Ant1-5270-5230~5249-PAS S	NTVN-11AX40MIMO-Ant2-5270-5230~5249-PAS S
 02:59:49 PM 03/16/2026	 02:56:11 PM 03/16/2026
NTVN-11AX40MIMO-Ant3-5270-5230~5249-PAS S	NTVN-11AX40MIMO-Ant1-5270-5249~5250-PAS S