

Appendix A: Frequency Error


Test Graphs





Appendix B: Antenna Power

Test Graphs







NTNV_BLE_2M_Ant1_2402



NTNV_BLE_2M_Ant1_2440





Appendix C: Occupied Bandwidth

Test Graphs






NTNV_BLE_2M_Ant1_2402




NTNV_BLE_2M_Ant1_2440





Appendix D: Spread Bandwidth

Test Graphs






NTNV_BLE_2M_Ant1_2402



NTNV_BLE_2M_Ant1_2440





Appendix E: Spurious Emission of TX

Test Graphs








NTNV_BLE_1M_Ant1_2402_2483.5~2496.5




NTNV_BLE_1M_Ant1_2402_2496.5~13000










NTNV_BLE_1M_Ant1_2440_2483.5~2496.5




NTNV_BLE_1M_Ant1_2440_2496.5~13000











NTNV_BLE_1M_Ant1_2480_2483.5~2496.5



NTNV_BLE_1M_Ant1_2480_2496.5~13000












NTNV_BLE_2M_Ant1_2440_2483.5~2496.5



NTNV_BLE_2M_Ant1_2440_2496.5~13000








NTNV_BLE_2M_Ant1_2480_2483.5~2496.5



NTNV_BLE_2M_Ant1_2480_2496.5~13000




Appendix F: Spurious Emission of RX

Test Graphs









NTNV_BLE_1M_Ant1_2440_1000~12500




NTNV_BLE_1M_Ant1_2480_30~1000







NTNV_BLE_2M_Ant1_2440_30~1000



NTNV_BLE_2M_Ant1_2440_1000~12500

