






NTNV-11N40SISO-Ant2-5190-5278.4~26000-PA
SS




NTNV-11N40SISO-Ant3-5190-5278.4~26000-PA
SS








NTNV-11N40SISO-Ant1-5230-30~5141.6-PASS



NTNV-11N40SISO-Ant2-5230-30~5141.6-PASS




NTNV-11N40SISO-Ant3-5230-30~5141.6-PASS	NTNV-11N40SISO-Ant1-5230-5141.6~5150-PASS
	
NTNV-11N40SISO-Ant2-5230-5141.6~5150-PASS	NTNV-11N40SISO-Ant3-5230-5141.6~5150-PASS
	
NTNV-11N40SISO-Ant1-5230-5250~5251-See table below	NTNV-11N40SISO-Ant2-5230-5250~5251-See table below




11:29:17 PM 02/03/2026

NTNV-11N40SISO-Ant3-5230-5250~5251-See table below




11:35:01 PM 02/03/2026

NTNV-11N40SISO-Ant1-5230-5251~5270-See table below




02:10:08 AM 02/03/2026

NTNV-11N40SISO-Ant2-5230-5251~5270-PASS




11:29:58 PM 02/03/2026

NTNV-11N40SISO-Ant3-5230-5251~5270-PASS







11:35:33 PM 02/03/2026







02:10:18 AM 02/03/2026





NTNV-11N40SISO-Ant1-5230-5270~5278.4-See table below	NTNV-11N40SISO-Ant2-5230-5270~5278.4-PAS S
NTNV-11N40SISO-Ant3-5230-5270~5278.4-PAS S	NTNV-11N40SISO-Ant1-5230-5278.4~26000-PA SS
NTNV-11N40SISO-Ant2-5230-5278.4~26000-PA SS	NTNV-11N40SISO-Ant3-5230-5278.4~26000-PA SS








NTNV-11N40MIMO-Ant2-5190-5141.6~5150-PA SS	NTNV-11N40MIMO-Ant3-5190-5141.6~5150-PA SS
 <p>06:25:32 AM 02/04/2026</p>	 <p>06:27:43 AM 02/04/2026</p>
NTNV-11N40MIMO-Ant1-5190-5250~5251-PASS	NTNV-11N40MIMO-Ant2-5190-5250~5251-PASS
 <p>06:29:55 AM 02/04/2026</p>	 <p>06:25:43 AM 02/04/2026</p>
NTNV-11N40MIMO-Ant3-5190-5250~5251-PASS	NTNV-11N40MIMO-Ant1-5190-5251~5270-PASS







<p>NTNV-11N40MIMO-Ant3-5190-5270~5278.4-PA</p> <p>SS</p>  <p>06/28/17 AM 02/04/2026</p>	<p>NTNV-11N40MIMO-Ant1-5190-5278.4~26000-P</p> <p>ASS</p>  <p>06/30/28 AM 02/04/2026</p>
<p>NTNV-11N40MIMO-Ant2-5190-5278.4~26000-P</p> <p>ASS</p>  <p>09/55/36 AM 02/04/2026</p>	<p>NTNV-11N40MIMO-Ant3-5190-5278.4~26000-P</p> <p>ASS</p>  <p>09/56/59 AM 02/04/2026</p>
<p>NTNV-11N40MIMO-Ant1-5230-30~5141.6-PASS</p>	<p>NTNV-11N40MIMO-Ant2-5230-30~5141.6-PASS</p>




 <p>09:55:22 PM 02/04/2026</p>	 <p>09:55:46 PM 02/04/2026</p>
NTNV-11N40MIMO-Ant3-5230-30~5141.6-PASS	NTNV-11N40MIMO-Ant1-5230-5141.6~5150-PA SS
 <p>09:57:09 PM 02/04/2026</p>	 <p>09:58:33 PM 02/04/2026</p>
NTNV-11N40MIMO-Ant2-5230-5141.6~5150-PA SS	NTNV-11N40MIMO-Ant3-5230-5141.6~5150-PA SS

 <p>09:55:57 PM 02/04/2026</p>	 <p>09:57:20 PM 02/04/2026</p>
NTNV-11N40MIMO-Ant1-5230-5250~5251-See table below	
 <p>09:58:43 PM 02/04/2026</p>	 <p>09:58:07 PM 02/04/2026</p>
NTNV-11N40MIMO-Ant1-5230-5251~5270-PASS	




<div>NTNV-11N40MIMO-Ant3-5230-5270~5278.4-PA</div> <div>SS</div> <div></div> <div>09:57:53 PM 02/04/2026</div>	<div>NTNV-11N40MIMO-Ant1-5230-5278.4~26000-P</div> <div>ASS</div> <div></div> <div>10:01:52 PM 02/04/2026</div>
<div>NTNV-11N40MIMO-Ant2-5230-5278.4~26000-P</div> <div>ASS</div> <div></div> <div>11:59:46 PM 02/02/2026</div>	<div>NTNV-11N40MIMO-Ant3-5230-5278.4~26000-P</div> <div>ASS</div> <div></div> <div>02:15:26 AM 02/03/2026</div>
<div>NTNV-11AC20SISO-Ant1-5180-30~5142-PASS</div>	<div>NTNV-11AC20SISO-Ant2-5180-30~5142-PASS</div>

 <p>11:52:49 PM 02/03/2026</p>	 <p>11:59:57 PM 02/03/2026</p>
NTNV-11AC20SISO-Ant3-5180-30~5142-See table below	NTNV-11AC20SISO-Ant1-5180-5142~5150-See table below
 <p>02:15:37 AM 02/03/2026</p>	 <p>11:32:59 PM 02/03/2026</p>
NTNV-11AC20SISO-Ant2-5180-5142~5150-PAS S	NTNV-11AC20SISO-Ant3-5180-5142~5150-See table below



 <p>NTVN-11AC20SISO-Ant1-5180-5250~5251-PAS S</p>	 <p>NTVN-11AC20SISO-Ant2-5180-5250~5251-PAS S</p>
 <p>NTVN-11AC20SISO-Ant3-5180-5250~5251-PAS S</p>	 <p>NTVN-11AC20SISO-Ant1-5180-5251~5260-PAS S</p>


NTNV-11AC20SISO-Ant2-5180-5251~5260-PAS S	NTNV-11AC20SISO-Ant3-5180-5251~5260-PAS S
NTNV-11AC20SISO-Ant1-5180-5260~5266.7-PA SS	NTNV-11AC20SISO-Ant2-5180-5260~5266.7-PA SS


NTNV-11AC20SISO-Ant3-5180-5260~5266.7-PA SS	NTNV-11AC20SISO-Ant1-5180-5266.7~26000-P ASS
NTNV-11AC20SISO-Ant2-5180-5266.7~26000-S ee table below	NTNV-11AC20SISO-Ant3-5180-5266.7~26000-S ee table below




<div>NTNV-11AC20SISO-Ant2-5200-5142~5150-PAS</div> <div>S</div> <div></div>	<div>NTNV-11AC20SISO-Ant3-5200-5142~5150-PAS</div> <div>S</div> <div></div>
<div>NTNV-11AC20SISO-Ant1-5200-5250~5251-PAS</div> <div>S</div> <div></div>	<div>NTNV-11AC20SISO-Ant2-5200-5250~5251-PAS</div> <div>S</div> <div></div>
<div>NTNV-11AC20SISO-Ant3-5200-5250~5251-PAS</div> <div>S</div> <div></div>	<div>NTNV-11AC20SISO-Ant1-5200-5251~5260-PAS</div> <div>S</div> <div></div>

 <p>02:23:19 AM 02/03/2026</p>	 <p>11:39:27 PM 02/03/2026</p>
NTNV-11AC20SISO-Ant2-5200-5251~5260-PAS S	NTNV-11AC20SISO-Ant3-5200-5251~5260-PAS S
 <p>11:44:42 PM 02/03/2026</p>	 <p>02:23:30 AM 02/03/2026</p>
NTNV-11AC20SISO-Ant1-5200-5260~5266.7-PA SS	NTNV-11AC20SISO-Ant2-5200-5260~5266.7-PA SS






11:47:44 AM 02/02/2026




02:28:14 AM 02/03/2026

NTNV-11AC20SISO-Ant1-5220-30~5142-PASS

NTNV-11AC20SISO-Ant2-5220-30~5142-PASS




11:45:00 AM 02/03/2026



11:47:55 AM 02/02/2026

NTNV-11AC20SISO-Ant3-5220-30~5142-PASS

NTNV-11AC20SISO-Ant1-5220-5142~5150-PASS



02:28:25 AM 02/03/2026







11:45:11 AM 02/03/2026





<div>NTNV-11AC20SISO-Ant2-5220-5142~5150-PAS</div> <div>S</div> <div></div>	<div>NTNV-11AC20SISO-Ant3-5220-5142~5150-PAS</div> <div>S</div> <div></div>
<div>NTNV-11AC20SISO-Ant1-5220-5250~5251-PAS</div> <div>S</div> <div></div>	<div>NTNV-11AC20SISO-Ant2-5220-5250~5251-PAS</div> <div>S</div> <div></div>
<div>NTNV-11AC20SISO-Ant3-5220-5250~5251-PAS</div> <div>S</div> <div></div>	<div>NTNV-11AC20SISO-Ant1-5220-5251~5260-PAS</div> <div>S</div> <div></div>




NTNV-11AC20SISO-Ant2-5220-5251~5260-PAS S	NTNV-11AC20SISO-Ant3-5220-5251~5260-PAS S
NTNV-11AC20SISO-Ant1-5220-5260~5266.7-PA SS	NTNV-11AC20SISO-Ant2-5220-5260~5266.7-PA SS


NTVN-11AC20SISO-Ant3-5220-5260~5266.7-PA SS	NTVN-11AC20SISO-Ant1-5220-5266.7~26000-P ASS
NTVN-11AC20SISO-Ant2-5220-5266.7~26000-P ASS	NTVN-11AC20SISO-Ant3-5220-5266.7~26000-P ASS







<p>NTNV-11AC20SISO-Ant2-5240-5142~5150-PAS</p> <p>S</p>  <p>11:55:05 PM 02/02/2026</p>	<p>NTNV-11AC20SISO-Ant3-5240-5142~5150-PAS</p> <p>S</p>  <p>02:36:12 AM 02/03/2026</p>
<p>NTNV-11AC20SISO-Ant1-5240-5250~5250.2-Se</p> <p>e table below</p>  <p>11:59:49 PM 02/03/2026</p>	<p>NTNV-11AC20SISO-Ant2-5240-5250~5250.2-Se</p> <p>e table below</p>  <p>11:59:45 PM 02/02/2026</p>
<p>NTNV-11AC20SISO-Ant3-5240-5250~5250.2-Se</p> <p>e table below</p>	<p>NTNV-11AC20SISO-Ant1-5240-5250.2~5251-PA</p> <p>SS</p>



 <p>02:56:53 AM 02/03/2026</p>	 <p>12:00:30 AM 02/04/2026</p>
NTNV-11AC20SISO-Ant2-5240-5250.2~5251-PA SS	NTNV-11AC20SISO-Ant3-5240-5250.2~5251-PA SS
 <p>11:55:56 PM 02/03/2026</p>	 <p>02:37:03 AM 02/03/2026</p>
NTNV-11AC20SISO-Ant1-5240-5251~5260-PAS S	NTNV-11AC20SISO-Ant2-5240-5251~5260-PAS S





 <p>12:00:40 AM 02/04/2026</p>	 <p>11:58:06 AM 02/02/2025</p>
NTNV-11AC20SISO-Ant3-5240-5251~5260-PAS S	NTNV-11AC20SISO-Ant1-5240-5260~5266.7-PA SS
 <p>02:37:14 AM 02/03/2026</p>	 <p>12:00:51 AM 02/04/2026</p>
NTNV-11AC20SISO-Ant2-5240-5260~5266.7-PA SS	NTNV-11AC20SISO-Ant3-5240-5260~5266.7-PA SS









NTNV-11AC20MIMO-Ant3-5180-5142~5150-PAS S	NTNV-11AC20MIMO-Ant1-5180-5250~5251-PAS S
 <p>10:25:05 PM 02/04/2026</p>	 <p>10:26:29 PM 02/04/2026</p>
NTNV-11AC20MIMO-Ant2-5180-5250~5251-PAS S	NTNV-11AC20MIMO-Ant3-5180-5250~5251-PAS S
 <p>10:23:53 PM 02/04/2026</p>	 <p>10:25:16 PM 02/04/2026</p>
NTNV-11AC20MIMO-Ant1-5180-5251~5260-PAS S	NTNV-11AC20MIMO-Ant2-5180-5251~5260-PAS S





 <p>10:26:40 PM 02/04/2026</p>	 <p>10:24:03 PM 02/04/2026</p>
NTNV-11AC20MIMO-Ant3-5180-5251~5260-PAS S	NTNV-11AC20MIMO-Ant1-5180-5260~5266.7-P ASS
 <p>10:25:27 PM 02/04/2026</p>	 <p>10:26:49 PM 02/04/2026</p>
NTNV-11AC20MIMO-Ant2-5180-5260~5266.7-P ASS	NTNV-11AC20MIMO-Ant3-5180-5260~5266.7-P ASS


 <p>NTVN-11AC20MIMO-Ant1-5180-5266.7~26000- PASS</p>	 <p>NTVN-11AC20MIMO-Ant2-5180-5266.7~26000- PASS</p>
 <p>NTVN-11AC20MIMO-Ant3-5180-5266.7~26000- PASS</p>	 <p>NTVN-11AC20MIMO-Ant1-5200-30~5142-PASS</p>




<div>NTNV-11AC20MIMO-Ant3-5200-5142~5150-PAS</div> <div>S</div> <div></div> <div>10:34:37 PM 02/04/2026</div>	<div>NTNV-11AC20MIMO-Ant1-5200-5250~5251-PAS</div> <div>S</div> <div></div> <div>10:36:00 PM 02/04/2026</div>
<div>NTNV-11AC20MIMO-Ant2-5200-5250~5251-PAS</div> <div>S</div> <div></div> <div>10:33:24 PM 02/04/2026</div>	<div>NTNV-11AC20MIMO-Ant3-5200-5250~5251-PAS</div> <div>S</div> <div></div> <div>10:34:47 PM 02/04/2026</div>
<div>NTNV-11AC20MIMO-Ant1-5200-5251~5260-PAS</div> <div>S</div> <div></div> <div></div>	<div>NTNV-11AC20MIMO-Ant2-5200-5251~5260-PAS</div> <div>S</div> <div></div> <div></div>

 <p>10:36:11 PM 02/04/2026</p>	 <p>10:35:39 PM 02/04/2026</p>
NTNV-11AC20MIMO-Ant3-5200-5251~5260-PAS S	NTNV-11AC20MIMO-Ant1-5200-5260~5266.7-P ASS
 <p>10:36:58 PM 02/04/2026</p>	 <p>10:36:21 PM 02/04/2026</p>
NTNV-11AC20MIMO-Ant2-5200-5260~5266.7-P ASS	NTNV-11AC20MIMO-Ant3-5200-5260~5266.7-P ASS

 <p>10:33:47 PM 02/04/2026</p>	 <p>10:35:10 PM 02/04/2026</p>
NTVN-11AC20MIMO-Ant1-5200-5266.7~26000-PASS	NTVN-11AC20MIMO-Ant2-5200-5266.7~26000-PASS
 <p>10:36:33 PM 02/04/2026</p>	 <p>10:41:56 PM 02/04/2026</p>
NTVN-11AC20MIMO-Ant3-5200-5266.7~26000-PASS	NTVN-11AC20MIMO-Ant1-5220-30~5142-PASS



NTVN-11AC20MIMO-Ant2-5220-30~5142-PASS



NTVN-11AC20MIMO-Ant3-5220-30~5142-PASS





NTVN-11AC20MIMO-Ant1-5220-5142~5150-PAS

S









NTVN-11AC20MIMO-Ant2-5220-5142~5150-PAS

S



<div>NTNV-11AC20MIMO-Ant3-5220-5142~5150-PAS</div> <div>S</div> <div></div>	<div>NTNV-11AC20MIMO-Ant1-5220-5250~5251-PAS</div> <div>S</div> <div></div>
<div>NTNV-11AC20MIMO-Ant2-5220-5250~5251-PAS</div> <div>S</div> <div></div>	<div>NTNV-11AC20MIMO-Ant3-5220-5250~5251-PAS</div> <div>S</div> <div></div>
<div>NTNV-11AC20MIMO-Ant1-5220-5251~5260-PAS</div> <div>S</div> <div></div>	<div>NTNV-11AC20MIMO-Ant2-5220-5251~5260-PAS</div> <div>S</div> <div></div>

 <p>10:45:13 PM 02/04/2026</p>	 <p>10:42:39 PM 02/04/2026</p>
NTNV-11AC20MIMO-Ant3-5220-5251~5260-PAS S	NTNV-11AC20MIMO-Ant1-5220-5260~5266.7-P ASS
 <p>10:44:01 PM 02/04/2026</p>	 <p>10:45:24 PM 02/04/2026</p>
NTNV-11AC20MIMO-Ant2-5220-5260~5266.7-P ASS	NTNV-11AC20MIMO-Ant3-5220-5260~5266.7-P ASS

 <p>NTVN-11AC20MIMO-Ant1-5220-5266.7~26000-PASS</p>	 <p>NTVN-11AC20MIMO-Ant2-5220-5266.7~26000-PASS</p>
 <p>NTVN-11AC20MIMO-Ant3-5220-5266.7~26000-PASS</p>	 <p>NTVN-11AC20MIMO-Ant1-5240-30~5142-PASS</p>