form JP

-5G WiFi 需要分三个 band 写，不要合在一起

-WiFi 天线型号没统一

Reply：更新。

2、internal photos

-P3，天线没标正确位置，不要标天线接口

Reply：更新。

3、operation description

-缺 802.11ax 模式信息

-蓝牙版本也不对

Reply：更新。

4、WiFi 2.4G 报告

-P6，AX 模式支持哪些 RU，测试的是哪些，报告给出的又是哪些请描述清楚

Reply：P6 增加了备注。

802.11ax-HE40	3	7	11	MCS 0
Note 1: After scanning all modulation types and data rates for all test patterns, the above list was found to be the worst case. Note 2: 802.11ax full RU and partial RU patterns were tested, but only the worst case (full RU) was reported.				

-P21, 40M 带宽的限值错了

Reply：更新报告。

-P82，天线增益怎么写着 0 又写着 1.83

Reply：更新报告。

5、WiFi 5G 报告

複製禁止

- P6，AX 模式支持哪些 RU，测试的是哪些，报告给出的又是哪些请描述清楚

Reply：P6 增加了备注。

802.11ac-VHT80/ax-HE80	/	5210	/	MCS 0
Note 1: After scanning all modulation types and data rates for all test patterns, the above list was found to be the worst case.				
Note 2: 802.11ax full RU and partial RU patterns were tested, but only the worst case (full RU) was reported.				

-P47/48，限值错误

Reply：更新报告。

-P51/52，确认限值，如果样机真有 TPC，需要增加测试

Reply：不支持 TPC，在第四页加备注

	6 for 802.11n (HT40), 802.11ac (VHT40)/ax(HE40) 3 for 802.11ac (VHT80)/ax(HE80)
Antenna Type	PIFA antenna
Antenna Gain	Ant 0: 4.86dBi Ant 1: 4.08dBi
TPC Function	Not Support

複製禁止