























NTNV-11N40MIMO-Ant1-2462-1000~2387-PASS




04:06:50 AM 01/31/2026

NTNV-11N40MIMO-Ant2-2462-1000~2387-PASS




04:10:30 AM 01/31/2026

NTNV-11N40MIMO-Ant1-2462-2387~2400-PASS



04:07:05 AM 01/31/2026


NTNV-11N40MIMO-Ant2-2462-2387~2400-PASS



04:10:45 AM 01/31/2026

NTNV-11N40MIMO-Ant1-2462-2483.5~2496.5-PA


SS



04:07:15 AM 01/31/2026


NTNV-11N40MIMO-Ant2-2462-2483.5~2496.5-PA


SS







04:10:55 AM 01/31/2026

Hotline:400-6788-333 www.cti-cert.com E-mail:info@cti-cert.com Complaint call:0755-33681700 Complaint E-mail:complaint@cti-cert.com











NTNV-11AX20SISO-Ant1-2442-2387~2400-PASS  12:01:47 AM 01/31/2026	NTNV-11AX20SISO-Ant2-2442-2387~2400-PASS  01:32:41 AM 01/31/2026
NTNV-11AX20SISO-Ant1-2442-2483.5~2496.5-PA SS  12:01:59 AM 01/31/2026	NTNV-11AX20SISO-Ant2-2442-2483.5~2496.5-PA SS  01:32:51 AM 01/31/2026
NTNV-11AX20SISO-Ant1-2442-2496.5~13000-PA SS	NTNV-11AX20SISO-Ant2-2442-2496.5~13000-PA SS





NTNV-11AX20SISO-Ant1-2472-2483.5~2496.5-Se e table below	NTNV-11AX20SISO-Ant2-2472-2483.5~2496.5-Se e table below
NTNV-11AX20SISO-Ant1-2472-2496.5~13000-PA SS	NTNV-11AX20SISO-Ant2-2472-2496.5~13000-PA SS







NTNV-11AX20MIMO-Ant1-2412-2483.5~2496.5-P ASS	NTNV-11AX20MIMO-Ant2-2412-2483.5~2496.5-PA SS
	
NTNV-11AX20MIMO-Ant1-2412-2496.5~13000-PA SS	NTNV-11AX20MIMO-Ant2-2412-2496.5~13000-PA SS
	
NTNV-11AX20MIMO-Ant1-2442-30~1000-PASS	NTNV-11AX20MIMO-Ant2-2442-30~1000-PASS












NTNV-11AX40SISO-Ant1-2422-2387~2400-PASS  12:13:19 AM 01/31/2026	NTNV-11AX40SISO-Ant2-2422-2387~2400-PASS  02:00:56 AM 01/31/2026
NTNV-11AX40SISO-Ant1-2422-2483.5~2496.5-PA SS  12:13:30 AM 01/31/2026	NTNV-11AX40SISO-Ant2-2422-2483.5~2496.5-PA SS  02:01:07 AM 01/31/2026
NTNV-11AX40SISO-Ant1-2422-2496.5~13000-PA SS	NTNV-11AX40SISO-Ant2-2422-2496.5~13000-PA SS







NTNV-11AX40SISO-Ant1-2462-30~1000-PASS




NTNV-11AX40SISO-Ant2-2462-30~1000-PASS




NTNV-11AX40SISO-Ant1-2462-1000~2387-PASS




NTNV-11AX40SISO-Ant2-2462-1000~2387-See
table below








NTNV-11AX40SISO-Ant1-2462-2387~2400-PASS




NTNV-11AX40SISO-Ant2-2462-2387~2400-PASS



NTNV-11AX40SISO-Ant1-2462-2483.5~2496.5-Se e table below	NTNV-11AX40SISO-Ant2-2462-2483.5~2496.5-PA SS
	
NTNV-11AX40SISO-Ant1-2462-2496.5~13000-PA SS	NTNV-11AX40SISO-Ant2-2462-2496.5~13000-See table below
	
NTNV-11AX40MIMO-Ant1-2422-30~1000-PASS	NTNV-11AX40MIMO-Ant2-2422-30~1000-PASS






NTNV-11AX40MIMO-Ant1-2442-1000~2387-PASS




06:17:44 AM 01/31/2026

NTNV-11AX40MIMO-Ant2-2442-1000~2387-PASS




06:21:23 AM 01/31/2026

NTNV-11AX40MIMO-Ant1-2442-2387~2400-PASS




06:17:59 AM 01/31/2026

NTNV-11AX40MIMO-Ant2-2442-2387~2400-PASS




06:21:38 AM 01/31/2026

NTNV-11AX40MIMO-Ant1-2442-2483.5~2496.5-PASS








06:18:10 AM 01/31/2026

NTNV-11AX40MIMO-Ant2-2442-2483.5~2496.5-PASS



06:21:48 AM 01/31/2026



NTNV-11AX40MIMO-Ant1-2462-2387~2400-PASS	NTNV-11AX40MIMO-Ant2-2462-2387~2400-PASS
	
NTNV-11AX40MIMO-Ant1-2462-2483.5~2496.5-PASS	NTNV-11AX40MIMO-Ant2-2462-2483.5~2496.5-PASS
	
NTNV-11AX40MIMO-Ant1-2462-2496.5~13000-PASS	NTNV-11AX40MIMO-Ant2-2462-2496.5~13000-PASS
