


Antenna 1_ ANP6Y-100085(Main),ANP6Y-100086(Aux), ACON,2016/4/13


Main :



Aux :




Antenna 2_ ANP6Y-100085(Main),ANP6Y-100086(Aux) , ACON, 2016/4/13



Antenna 3_ 81EAA515.G17(Main),81EAA515.G18(Aux), ACON, 2016/4/13


Main :




Aux :




■ Antenna 4_ 81EAA515.G17(Main),81EAA515.G18(Aux), ACON, 2016/4/13



Antenna 5_ WA-P-LBLB-04-029(Main),WA-P-LBLB-04-029(Aux), INPAQ TECHNOLOGY CO., LTD., 2016/4/13



Antenna 6_ WA-F-LB-02-068(Main),WA-F-LB-02-069(Aux), INPAQ TECHNOLOGY CO., LTD., 2016/4/13




Antenna 7_ LA05RF845-1H(Main),LA05RF845-1H(Aux), LUXSHARE, 2016/4/13




■ Antenna 8_ LA05RF884-1H(Main),LA05RF884-2H(Aux), LUXSHARE, 2016/4/13


Tx1 :




Tx2:



Antenna 9_ WA-P-LB-02-262(Main), INPAQ TECHNOLOGY CO., LTD., 2016/4/13




■ Antenna 10_ LA05RF865-1H(Main), LUXSHARE, 2016/4/13



Antenna 11_ WA-P-LB-02-295(Main),WA-P-LB-01-139(Aux), INPAQ, 2016/4/13


Tx1 :



Tx2:




■ Antenna 12_ LA05RF872-1H, LUXSHARE, 2016/4/13



- Antenna 13_ WA-P-LB-02-309(Main),WA-P-LB-01-144(Aux), INPAQ TECHNOLOGY CO., LTD, 2016/4/13

Tx1 :



Tx2:

