



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (31) / (48) Pages


APPENDIX C – ANT2 data

Frequency tolerance


Ch.27: 2 485MHz



Ch.28: 2 490MHz



Ch.29: 2 495MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (32) / (48) Pages


Occupied bandwidth

Ch.27: 2 485MHz




Spread bandwidth


Ch.27: 2 485MHz




Ch.28: 2 490MHz




Ch.28: 2 490MHz



Ch.29: 2 495MHz



Ch.29: 2 495MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2019-01044
Page (33) / (48) Pages

RF output power


Ch.27: 2 485MHz



Ch.28: 2 490MHz



Ch.29: 2 495MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (34) / (48) Pages

ON/OFF time






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (35) / (48) Pages


Unwanted(Spurious) emission

Ch.27: 2 485 MHz


30MHz-2458MHz




2458MHz-2471MHz



2497MHz-2510MHz



2510MHz-12500MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2019-01044
Page (36) / (48) Pages

Ch.28: 2 490 MHz


30MHz-2458MHz




2458MHz-2471MHz



2497MHz-2510MHz



2510MHz-12500MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2019-01044
Page (37) / (48) Pages

Ch.29: 2 495 MHz


30MHz-2458MHz




2458MHz-2471MHz



2497MHz-2510MHz



2510MHz-12500MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (38) / (48) Pages


Receiver Spurious Emission

Ch.27: 2 485 MHz


30MHz-1GHz



1GHz-10GHz



10GHz-12.5GHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (39) / (48) Pages

Ch.28: 2 490 MHz


30MHz-1GHz



1GHz-10GHz




10GHz-12.5GHz




Ch.29: 2 495 MHz


30MHz-1GHz



1GHz-10GHz



10GHz-12.5GHz





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (40) / (48) Pages


APPENDIX D – ANT3 data

Frequency tolerance


Ch.27: 2 485MHz



Ch.28: 2 490MHz



Ch.29: 2 495MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (41) / (48) Pages


Occupied bandwidth

Ch.27: 2 485MHz




Spread bandwidth


Ch.27: 2 485MHz




Ch.28: 2 490MHz




Ch.28: 2 490MHz



Ch.29: 2 495MHz



Ch.29: 2 495MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2019-01044
Page (42) / (48) Pages

RF output power


Ch.27: 2 485MHz



Ch.28: 2 490MHz



Ch.29: 2 495MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (43) / (48) Pages

ON/OFF time






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (44) / (48) Pages


Unwanted(Spurious) emission

Ch.27: 2 485 MHz


30MHz-2458MHz




2458MHz-2471MHz



2497MHz-2510MHz



2510MHz-12500MHz






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2019-01044
Page (45) / (48) Pages

Ch.28: 2 490 MHz


30MHz-2458MHz




2458MHz-2471MHz



2497MHz-2510MHz



2510MHz-12500MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2019-01044
Page (46) / (48) Pages

Ch.29: 2 495 MHz


30MHz-2458MHz




2458MHz-2471MHz



2497MHz-2510MHz



2510MHz-12500MHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2019-01044
Page (47) / (48) Pages


Receiver Spurious Emission

Ch.27: 2 485 MHz


30MHz-1GHz



1GHz-10GHz



10GHz-12.5GHz






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2019-01044
Page (48) / (48) Pages

Ch.28: 2 490 MHz


30MHz-1GHz



1GHz-10GHz




10GHz-12.5GHz



Ch.29: 2 495 MHz


30MHz-1GHz



1GHz-10GHz



10GHz-12.5GHz





CTK Co., Ltd.
The Prime Leader of Global Regulatory Certification

CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea

Tel: +82-31-339-9970

Fax: +82-31-624-9501

Report No.:

CTK-2019-01044

Page (49) / (48) Pages