



Appendix A: Frequency Error


Test Graphs






Appendix B: Antenna Power


Test Graphs






Appendix C: Occupied Bandwidth


Test Graphs






Appendix D: Spread Bandwidth

Test Graphs







Appendix E: Spurious Emission of TX

Test Graphs








NTLV_BLE_1M_Ant1_2402_2387~2400




NTLV_BLE_1M_Ant1_2402_2483.5~2496.5










NTLV_BLE_1M_Ant1_2440_2387~2400




NTLV_BLE_1M_Ant1_2440_2483.5~2496.5








NTLV_BLE_1M_Ant1_2480_2387~2400



NTLV_BLE_1M_Ant1_2480_2483.5~2496.5




NTLV_BLE_1M_Ant1_2480_2496.5~13000


Appendix F: Spurious Emission of RX

Test Graphs





NTLV_BLE_1M_Ant1_2440_30~1000



NTLV_BLE_1M_Ant1_2440_1000~12500

