



? nnjgcb rm dpm l r md rp_l q k grcp



? nnjgcb rm dpm l r md pcacgt cp

? nnjgcb rm _ai md Pcacgt cp

Name of Product:	BFAC Receiver - 20031	Name of Mfg.:	Fan Innovations
Address of Mfg.:	Hixson, TN USA	Serial Number:	<serial number>
FCC ID:	2A2WP-20031	Canada IC:	27702-20031
FCC Statement: This device complies with part 15 of the FCC rules and with Innovation, Science and Economic Development Canada's license-exempt RSS(s). Operation is subject to the following two conditions: 1. This device may not cause interference. 2. This device must accept any interference, including interference that may cause undesired operation of the device.			

20032



Applied to the mouth piece wire



WARNING!

ELECTRIC SHOCK can kill. UNEXPECTED WELD OUTPUT can cause ELECTRIC SHOCK. Wireless remote control can turn weld output on from distant locations.

- Disconnect receiver from remote receptacle and remove battery from remote control before servicing equipment.
- Read and follow all labels and the Owner's Manual carefully.

20059

Applied to the side of the housing on the controller and transmitter

Name of Product:	BFAC Transmitter - 20030	Name of Mfg.:	Fan Innovations
Address of Mfg.:	Hixson, TN USA	Serial Number:	<serial number>
FCC ID:	2A2WP-20030	Canada IC:	27702-20030
FCC Statement:	This device complies with part 15 of the FCC rules and with Innovation, Science and Economic Development Canada's license-exempt RSS(s). Operation is subject to the following two conditions: 1. This device may not cause interference. 2. This device must accept any interference, including interference that may cause undesired operation of the device.		

20034

? nnjgcb rm ` _ai md rp_l q k grcp