

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1



Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


Worst Case Position

CONTROLLER, ID KEY


Below 30MHz : X-axis
Above 30MHz (Horizontal: Y-axis /
Vertical: Y-axis)
X-axis



Y-axis




Z-axis




ID Receiving antenna

Below 30MHz : X-axis
Above 30MHz (Horizontal: X-axis /
Vertical: X-axis)
X-axis



Y-axis




Z-axis



Worst Case Position


Insert Key



Not insert Key (worst)



Without Key Cylinder and Steel Frame



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124