





40MHz\_15kHz\_3500MHz\_DFT-s-OFDM QPSK\_RB216@0 -42.94 dBm




ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 00:07:01

40MHz\_15kHz\_3530MHz\_DFT-s-OFDM QPSK\_RB1@0 -27.48 dBm




ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 00:09:10

40MHz\_15kHz\_3530MHz\_DFT-s-OFDM QPSK\_RB1@0 -43.14 dBm




ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 00:08:25

40MHz\_15kHz\_3530MHz\_DFT-s-OFDM QPSK\_RB1@215 -43.16 dBm




ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 00:09:45

40MHz\_15kHz\_3530MHz\_DFT-s-OFDM QPSK\_RB1@215 -29.72 dBm




ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 00:10:39

40MHz\_15kHz\_3530MHz\_DFT-s-OFDM QPSK\_RB216@0 -29.96 dBm




ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 00:11:59

40MHz\_15kHz\_3530MHz\_DFT-s-OFDM QPSK\_RB216@0 -42.25 dBm




ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 00:11:13

40MHz\_30kHz\_3470MHz\_DFT-s-OFDM QPSK\_RB1@0 -30.41 dBm




ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 18:06:25

40MHz\_30kHz\_3470MHz\_DFT-s-OFDM QPSK\_RB1@0 -43.16 dBm




ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 18:05:40

40MHz\_30kHz\_3470MHz\_DFT-s-OFDM QPSK\_RB1@105 -27.40 dBm




ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 18:07:24

40MHz\_30kHz\_3470MHz\_DFT-s-OFDM QPSK\_RB1@105 -42.74 dBm



ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 18:06:50

40MHz\_30kHz\_3470MHz\_DFT-s-OFDM QPSK\_RB100@0 -29.99 dBm



ProjectNo.:SZ1231211-74617E Tester:Jim Cheng  
Date: 18.JAN.2024 18:08:22